

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/1/14	MAKE	KOBELCO	MODEL	LK40Z-2
SERIAL	RW00568			STAMP	RW2-00568
HR METER	3016	HR	Odometer	—	km YEAR YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	12.5/70-16 6RR

ENGINE : MODEL 3TNE84 S/N	
Oil leakage	FAIR · Attn
Blow-By	FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn
Oil	FAIR · Attn
Exhaust Color	FAIR · Attn
US EPA	YES · (NO)
OPERATION PUMP	
Sound	FAIR · Attn
Oil leakage	FAIR · Attn
Power	FAIR · Attn
COOLING SYSTEM	
Radiator	FAIR · Attn
Oil Cooler	FAIR · Attn
TRANSMISSION & TRAVEL	
T/M TYPE	(PS) · DD
Transmission	FAIR · Attn
Travel	FAIR · Attn
FOOT BRAKE	FAIR · Attn
PARKING BRAKE	FAIR · Attn
INTERIOR See Photos. 写真参照	
Operator's Seat	FAIR · (Attn) 破れ大 TORN
Inside Cover	FAIR · (Attn) *1
Glasses	FAIR · Attn
AirCon	A/C · H/C · (H only) · C only · None
FRONT & CYLINDERS	
Arm	FAIR · (Attn) *2
Bell crank	FAIR · Attn
Bucket	FAIR · Attn
Articulate	FAIR · (Attn) シリンダーにじみあり CYLINDER: OIL OOZING

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
STEERING TYPE WHEEL STEERING / (COMMAND STEERING) / LEVER STEERING	
RIDE CONTROL	YES · (NO)
ATTACHMENTS	
STD BKT	(YES) · OTHER
BLADE	YES · (NO) Piping for Tilt YES · (NO)
COMMENT	
センターピンガタあり CENTER PIN: LOOSE	
センターピンボルト折損あり CENTER PIN BOLT: BROKEN	
*1 天井内張り剥がれあり INSIDE COVER OF CEILING: PEELED	
*2 右シリンダーにじみあり RIGHT CYLINDER: OIL OOZING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
2	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。