

INSPECTION SHEET 検品書  
BULLDOZER ブルドーザー

INSPECTION DATE	2025/3/27	MAKE	MITSUBISHI	MODEL	BD2J
SERIAL	JB510074		STAMP	2B510074	
HR METER	2299	HR	SHOE	300G	YEAR YR
BLADE	STRAIGHT / ST/TILT / PAT / ANGLE / OTHER		CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE	

<b>ENGINE : MODEL</b>		S/N	53021
Oil leakage	<input checked="" type="radio"/> FAIR · Attn		
Blow-By	<input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	<input checked="" type="radio"/> FAIR · Attn		
Oil	<input checked="" type="radio"/> FAIR · Attn		
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn		
US EPA	YES · <input checked="" type="radio"/> NO		
<b>OPERATION PUMP</b>			
Sound	<input checked="" type="radio"/> FAIR · Attn		
Oil leakage	<input checked="" type="radio"/> FAIR · Attn		
Power	<input checked="" type="radio"/> FAIR · Attn		
<b>COOLING SYSTEM</b>			
Radiator	<input checked="" type="radio"/> FAIR · Attn		
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn		
<b>TRANSMISSION &amp; TRAVEL</b>			
T/M TYPE	<input checked="" type="radio"/> PS · DD	DIFF. STEERING	YES · <input checked="" type="radio"/> NO
Transmission	<input checked="" type="radio"/> FAIR · Attn		
Travel	<input checked="" type="radio"/> FAIR · Attn		
<b>INTERIOR See Photos. 写真参照</b>			
INTERIOR COND.	CLEAN · <input checked="" type="radio"/> FAIR · DIRTY		
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn	破れあり HUGE CUTS	
Glasses	<input checked="" type="radio"/> FAIR · Attn		
AirCon	A/C · H/C · <input checked="" type="radio"/> H only · C only · None		
<b>BLADE &amp; CYLINDERS</b>			
BLADE	<input checked="" type="radio"/> FAIR · Attn		
CYLD.(R)	<input checked="" type="radio"/> FAIR · Attn		
CYLD.(L)	<input checked="" type="radio"/> FAIR · Attn		
TILT CYLD	<input checked="" type="radio"/> FAIR · Attn		
ANGLE CYLD	<input checked="" type="radio"/> FAIR · Attn		

<b>UNDERCARRIAGE See Photos. 写真参照</b>			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			4
<b>COMMENT</b>			
Ripper	MULTI · S/S	Shanks	PCS
Ripper CYLD.	<input checked="" type="radio"/> FAIR · Attn		
EQUALIZER BAR	<input checked="" type="radio"/> FAIR · Attn		
<b>COMMENT</b>			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。