

INSPECTION SHEET 検品書
WHEEL EXCAVATOR タイヤバックホー

INSPECTION DATE	2025/4/10	MAKE	KOBELCO	MODEL	SK100W		
SERIAL	YE-01944			STAMP	NOT FOUND		
HR METER	1678	HR	Odometer	43075	km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	9.00R20		

ENGINE : MODEL		S/N
Oil leakage	FAIR • Attn	
Blow-By	FAIR • Attn	A LITTLE • MIDDLE • SEVERE
Sound	FAIR • Attn	
Oil	FAIR • Attn	
Exhaust Color	FAIR • Attn	白煙あり WHITE FUMES
US EPA	YES • NO	
MAIN PUMP		
Sound	FAIR • Attn	
Oil leakage	FAIR • Attn	
Power	FAIR • Attn	
COOLING SYSTEM		
Radiator	FAIR • Attn	
Oil Cooler	FAIR • Attn	
OPERATING SYSTEM		
Swing	FAIR • Attn	ガタあり SWING: LOOSE
Travel	FAIR • Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN • FAIR • DIRTY	
Operator's Seat	FAIR • Attn	破れあり TORN
Glasses	FAIR • Attn	
AirCon	A/C • H/C • H only • C only • None	
BOOM / ARM / BKT		
Boom	FAIR • Attn	
Boom Cylinder	FAIR • Attn	左右油漏れ小 CYLINDERS: OIL LEAKING
Arm	FAIR • Attn	
Arm Cylinder	FAIR • Attn	油漏れ小 OIL LEAKING
BKT	FAIR • Attn	
BKT Cylinder	FAIR • Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR	FAIR • WORN • UNEVEN WEAR
COMMENT	
左右Fダンパー油漏れあり FRONT DAMPER CYLINDERS: OIL LEAKING	
BKT	STD / SLOPE / NARROW / SKELETON / OTHER()
Lever	LONG • WRIST
Multi	MULTI • 2 • NO
ARM-CRANE	YES • NO
BLADE	YES • NO
OFFSET	YES • NO
OFFSET Cylinder	FAIR • Attn
Piping	YES • NO Breaker only • Multi
OUTRIGGERS COND.	FAIR • Attn
COMMENT	
燃料タンク周り油汚れあり FUEL TANK: OIL STAINS	
噴射ノズル燃料漏れ小 INJECTION NOZZLE: FUEL LEAKING	
アクセルレバー不良、調整不可	
ACCELERATOR LEVER: MALFUNCTION	
(UNABLE TO CONTROL THE ENGINE SPEED)	
A/Cベルト欠 A/C: NO BELT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。