

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/3/27	MAKE	KOMATSU	MODEL	PC58UU-5
SERIAL	25311		STAMP	KMTPC221L04025311	
HR METER	4575	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	400R	

ENGINE : MODEL		S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · NO	
MAIN PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	
COOLING SYSTEM		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	
OPERATING SYSTEM		
Swing	FAIR · Attn	
Travel	FAIR · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · DIRTY	
Operator's Seat	FAIR · Attn	破れあり CUTS
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · None	
BOOM / ARM / BKT		
Boom	FAIR · Attn	ガタあり LOOSE
Boom Cylinder	FAIR · Attn	
Arm	FAIR · Attn	
Arm Cylinder	FAIR · Attn	
BKT	FAIR · Attn	
BKT Cylinder	FAIR · Attn	

UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4	
COMMENT		
ラバーシュー 摩耗あり RUBBER TRACKS: WORN		
BKT	☐ STD / ☐ SLOPE / ☐ NARROW / ☐ SKELETON / ☐ OTHER ()	
Lever	LONG ▪ ☒ WRIST	
Multi	☒ MULTI ▪ 2 ▪ NO	
ARM-CRANE	☒ YES ▪ NO	*1
BLADE	☒ YES ▪ NO	
OFFSET	☒ YES ▪ NO	*2
OFFSET Cylinder	☒ FAIR ▪ Attn	
Piping	YES ▪ ☒ NO	Breaker only ▪ Multi
COMMENT		
*1 モード入るがE524表示出っぱなし *1 "E524" ERROR DISPLAY (CRANE MODE: ABLE TO TURN ON) *2 干渉防止不良 ANTI-INTERFERENCE SYSTEM: MALFUNCTION		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。