

INSPECTION SHEET 検品書
WHEEL EXCAVATOR タイヤバックホー

INSPECTION DATE	2025/3/31	MAKE	HITACHI	MODEL	ZX125W
SERIAL	HCM11P00V00006108			STAMP	125W-6108
HR METER	3416	HR	Odometer	-	km YEAR YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	9.00-20

ENGINE : MODEL		S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · NO	
MAIN PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	
COOLING SYSTEM		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	
OPERATING SYSTEM		
Swing	FAIR · Attn	ガタあり SWING: LOOSE
Travel	FAIR · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · DIRTY	
Operator's Seat	FAIR · Attn	破れあり HUGE CUTS
Glasses	FAIR · Attn	*1
AirCon	A/C · H/C · H only · C only · None	
BOOM / ARM / BKT		
Boom	FAIR · Attn	
Boom Cylinder	FAIR · Attn	左サビあり LEFT CYLINDER: RUSTY
Arm	FAIR · Attn	
Arm Cylinder	FAIR · Attn	
BKT	FAIR · Attn	ガタあり LOOSE
BKT Cylinder	FAIR · Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR	FAIR · WORN · UNEVEN WEAR
COMMENT	
ワイヤー見えあり SOME INNER WIRES OF SOME TIRE: PARTLY BARED	
BKT	STD (SLOPE) NARROW / SKELETON / OTHER()
Lever	LONG · WRIST
Multi	MULTI · 2 · NO
ARM-CRANE	YES · NO
BLADE	YES · NO
OFFSET	YES · NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · NO Breaker only · Multi *2
OUTRIGGERS COND.	FAIR · Attn
COMMENT	
CABドア紐で固定あり DOOR: FIXING WITH SOME ROPE	
アクセルワイヤー不良、Pブレーキ、S警告灯消えない	
ACCELERATOR WIRE: MALFUNCTION,	
PARKING BRAKE LAMP & "S" WARNING LAMP: UNABLE TO GO OUT	
E/Gストップ: キーOFFだと出来ない、CAB内のE/Gストップレバーで停止する	
UNABLE TO STOP THE ENGINE BY THE KEY,	
NEED TO STOP THE ENGINE BY ENGINE STOP LEVER IN CAB	
*1 Fフレーム腐食あり、ドア上1枚欠	
*1 WINDSHIELD FRAME: CORRODED, SOME UPPER DOOR GLASS: MISSING	
*2 ペダル固着のため不明 PEDAL: STUCK	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。