

INSPECTION SHEET 検品書  
ROUGH TERRAIN CRANE ラフタークレーン

|                 |                |      |                   |        |           |
|-----------------|----------------|------|-------------------|--------|-----------|
| INSPECTION DATE | 2025/3/24      | MAKE | TADANO            | MODEL  | GR-120N-2 |
| SERIAL No.      | PLATE : FD1757 |      | STAMP : T005-0120 |        |           |
| HR METER        | 20375          | HR   | Odometer          | 133667 | km        |
| TIRE SIZE       | 275/80R22.5    |      | YEAR              | YR     |           |

| ENGINE : MODEL            |                                    | S/N                        |
|---------------------------|------------------------------------|----------------------------|
| Oil leakage               | FAIR · Attn                        |                            |
| Blow-By                   | FAIR · Attn                        | A LITTLE · MIDDLE · SEVERE |
| Sound                     | FAIR · Attn                        |                            |
| Oil                       | FAIR · Attn                        |                            |
| Exhaust Color             | FAIR · Attn                        |                            |
| OPERATION PUMP            |                                    |                            |
| Sound                     | FAIR · Attn                        |                            |
| Oil leakage               | FAIR · Attn                        |                            |
| Power                     | FAIR · Attn                        |                            |
| COOLING SYSTEM            |                                    |                            |
| Radiator                  | FAIR · Attn                        |                            |
| Oil Cooler                | FAIR · Attn                        |                            |
| OPERATING SYSTEM          |                                    |                            |
| Computer                  | OK · NG                            |                            |
| Swing                     | FAIR · Attn                        |                            |
| Travel                    | FAIR · Attn                        |                            |
| TRANSMISSION              |                                    |                            |
| Transmission              | FAIR · Attn                        |                            |
| No. OF GEARS              | 3                                  | GEARS                      |
| 4WD                       | 4WD · 6WD                          |                            |
| INTERIOR See Photos. 写真参照 |                                    |                            |
| INTERIOR COND.            | CLEAN · FAIR · DIRTY               |                            |
| Operator's Seat           | FAIR · Attn                        | シート破れあり HUGE CUT, HOLE     |
| Glasses                   | FAIR · Attn                        |                            |
| AirCon                    | A/C · H/C · H only · C only · None |                            |
| COMMENT                   |                                    |                            |
|                           |                                    |                            |
|                           |                                    |                            |
|                           |                                    |                            |
|                           |                                    |                            |

|                                                                      |  |                           |  |          |  |      |  |       |  |
|----------------------------------------------------------------------|--|---------------------------|--|----------|--|------|--|-------|--|
| BOOM                                                                 |  |                           |  |          |  |      |  |       |  |
| No. of Section                                                       |  | 6                         |  | SECTIONS |  |      |  |       |  |
| CRACK/ENFORCEMENT                                                    |  | FAIR                      |  | ▪ Attn   |  |      |  |       |  |
| DERRICKING CYL.                                                      |  | FAIR                      |  | ▪ Attn   |  |      |  |       |  |
| EXTENSION CYL.                                                       |  | FAIR                      |  | ▪ Attn   |  |      |  |       |  |
| JIB                                                                  |  | YES                       |  | ▪ NO     |  |      |  |       |  |
| JIB TYPE                                                             |  | STD                       |  | ▪ PWR    |  |      |  |       |  |
| MAIN & SUB WIRE                                                      |  | YES                       |  | ▪ NO     |  |      |  |       |  |
| HOOK                                                                 |  | 12t, BALL                 |  |          |  |      |  |       |  |
| UNDERCARRIAGE : See Photos. 写真参照                                     |  |                           |  |          |  |      |  |       |  |
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)         |  |                           |  |          |  |      |  | 1     |  |
| TIRE WEAR                                                            |  | FAIR ▪ WORN ▪ UNEVEN WEAR |  |          |  |      |  |       |  |
| COMMENT                                                              |  |                           |  |          |  |      |  |       |  |
|                                                                      |  |                           |  |          |  |      |  |       |  |
|                                                                      |  |                           |  |          |  |      |  |       |  |
| OUTRIGGERS                                                           |  |                           |  |          |  |      |  |       |  |
| OUTRIGGERS                                                           |  | X                         |  | ▪ H      |  |      |  |       |  |
| OUTRIGGERS COND.                                                     |  | FAIR                      |  | ▪ Attn   |  |      |  |       |  |
| Oil leakage (JACK CYL.)                                              |  | FRONT                     |  | L ▪ R    |  | REAR |  | L ▪ R |  |
| Oil leakage (SLIDE CYL.)                                             |  | FRONT                     |  | L ▪ R    |  | REAR |  | L ▪ R |  |
| COMMENT                                                              |  |                           |  |          |  |      |  |       |  |
|                                                                      |  |                           |  |          |  |      |  |       |  |
|                                                                      |  |                           |  |          |  |      |  |       |  |
|                                                                      |  |                           |  |          |  |      |  |       |  |
|                                                                      |  |                           |  |          |  |      |  |       |  |
|                                                                      |  |                           |  |          |  |      |  |       |  |
|                                                                      |  |                           |  |          |  |      |  |       |  |
|                                                                      |  |                           |  |          |  |      |  |       |  |
|                                                                      |  |                           |  |          |  |      |  |       |  |
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) |  |                           |  |          |  |      |  | 2     |  |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。