

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/4/4	MAKE	TADANO	MODEL	GR-120N-2
SERIAL No.	PLATE : FD2081			STAMP : T005-0411	
HR METER	21783	HR	Odometer	43027	km
TIRE SIZE	275/80R22.5			YEAR	YR

ENGINE : MODEL		S/N
Oil leakage	FAIR (Attn)	E/G下部にじみあり BOTTOM OF ENGINE: OIL OOZING
Blow-By	FAIR (Attn)	A LITTLE ・ MIDDLE ・ SEVERE
Sound	FAIR (Attn)	
Oil	FAIR (Attn)	
Exhaust Color	FAIR (Attn)	

OPERATION PUMP		
Sound	FAIR	Attn
Oil leakage	FAIR	Attn
Power	FAIR	Attn

COOLING SYSTEM		
Radiator	FAIR	Attn
Oil Cooler	FAIR	Attn

OPERATING SYSTEM		
Computer	OK · NG	
Swing	FAIR · Attn	
Travel	FAIR · Attn	

TRANSMISSION		
Transmission	FAIR	Attn
No. OF GEARS	3	GEARS
4WD	4WD	6WD

INTERIOR		See Photos. 写真参照	
INTERIOR COND.	CLEAN	FAIR	DIRTY
Operator's Seat	FAIR	Attn	
Glasses	FAIR	Attn	
AirCon	A/C	H/C	H only C only None

COMMENT	

BOOM		
No. of Section	6	SECTIONS
CRACK/ENFORCEMENT	FAIR	▪ Attn
DERRICKING CYL.	FAIR	▪ Attn
EXTENSION CYL.	FAIR	▪ Attn
JIB	YES	▪ NO
JIB TYPE	STD	▪ PWR
MAIN & SUB WIRE	YES	▪ NO
HOOK	12t, BALL	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

TIRE WEAR	FAIR • WORN • UNEVEN WEAR
-----------	---------------------------

COMMENT	

OUTRIGGERS		
OUTRIGGERS	X	H
OUTRIGGERS COND.	FAIR	Attn

Oil leakage (JACK CYL.)	FRONT	L · R	REAR	L · R
Oil leakage (SLIDE CYL.)	FRONT	L · R	REAR	L · R

COMMENT

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
---	----------

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。