

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

|                 |                                        |      |         |       |                   |
|-----------------|----------------------------------------|------|---------|-------|-------------------|
| INSPECTION DATE | 2025/4/3                               | MAKE | HITACHI | MODEL | ZX350LCK-5B       |
| SERIAL          | HCMDDDA5P00070737                      |      |         | STAMP | HCMDDDA5P00070737 |
| HR METER        | 9051                                   | HR   | YEAR    | YR    |                   |
| CAB/CNP         | ROPS CAB / CAB / ROPS CNP / CNP / NONE |      |         | SHOE  | 600G              |

|                           |       |      |                            |        |
|---------------------------|-------|------|----------------------------|--------|
| ENGINE : MODEL            |       | 6HK1 | S/N                        | 586543 |
| Oil leakage               | FAIR  | Attn |                            |        |
| Blow-By                   | FAIR  | Attn | A LITTLE · MIDDLE · SEVERE |        |
| Sound                     | FAIR  | Attn |                            |        |
| Oil                       | FAIR  | Attn |                            |        |
| Exhaust Color             | FAIR  | Attn |                            |        |
| US EPA                    | YES   | NO   |                            |        |
| MAIN PUMP                 |       |      |                            |        |
| Sound                     | FAIR  | Attn | 異音あり NOISES                |        |
| Oil leakage               | FAIR  | Attn | *1                         |        |
| Power                     | FAIR  | Attn |                            |        |
| COOLING SYSTEM            |       |      |                            |        |
| Radiator                  | FAIR  | Attn |                            |        |
| Oil Cooler                | FAIR  | Attn |                            |        |
| OPERATING SYSTEM          |       |      |                            |        |
| Swing                     | FAIR  | Attn |                            |        |
| Travel                    | FAIR  | Attn | *2                         |        |
| INTERIOR See Photos. 写真参照 |       |      |                            |        |
| INTERIOR COND.            | CLEAN | FAIR | DIRTY                      |        |
| Operator's Seat           | FAIR  | Attn | 破れ大 TORN                   |        |
| Glasses                   | FAIR  | Attn |                            |        |
| AirCon                    | A/C   | H/C  | H only                     | C only |
|                           |       |      |                            | None   |
| BOOM / ARM / BKT          |       |      |                            |        |
| Boom                      | FAIR  | Attn |                            |        |
| Boom Cylinder             | FAIR  | Attn |                            |        |
| Arm                       | FAIR  | Attn |                            |        |
| Arm Cylinder              | FAIR  | Attn |                            |        |
| BKT                       | FAIR  | Attn |                            |        |
| BKT Cylinder              | FAIR  | Attn |                            |        |

[illegible]

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。