

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/4/4	MAKE	KATO	MODEL	KR-25H-V7
SERIAL No.	PLATE : 5110187		STAMP : KRC005-0187		
HR METER	22032	HR	Odometer	108320	km
TIRE SIZE	385/95R25		YEAR	YR	

ENGINE : MODEL		S/N	
Oil leakage	FAIR	Attn	
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
OPERATION PUMP			
Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	
COOLING SYSTEM			
Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	
OPERATING SYSTEM			
Computer	OK	NG	
Swing	FAIR	Attn	
Travel	FAIR	Attn	
TRANSMISSION			
Transmission	FAIR	Attn	にじみあり OIL OOZING
No. OF GEARS	4	GEARS	
4WD	4WD	6WD	
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN	FAIR	DIRTY
Operator's Seat	FAIR	Attn	
Glasses	FAIR	Attn	
AirCon	A/C	H/C · H only · C only · None	
COMMENT			

BOOM						
No. of Section	4		SECTIONS			
CRACK/ENFORCEMENT	(FAIR)	▪ Attn				
DERRICKING CYL.	(FAIR)	▪ Attn				
EXTENSION CYL.	(FAIR)	▪ Attn				
JIB	(YES)	▪ NO				
JIB TYPE	STD	(PWR)				
MAIN & SUB WIRE	(YES)	▪ NO				
HOOKE	25t, BALL					
UNDERCARRIAGE : See Photos. 写真参照						
RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)						4
TIRE WEAR	(FAIR) ▪ WORN ▪ UNEVEN WEAR					
COMMENT						
OUTRIGGERS						
OUTRIGGERS	(X)	▪ H				
OUTRIGGERS COND.	(FAIR)	▪ Attn				
Oil leakage (JACK CYL.)	FRONT	L ▪ R	REAR	(L)	▪ R	
Oil leakage (SLIDE CYL.)	FRONT	L ▪ R	REAR	L ▪ R		
COMMENT						
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)						4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。