

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/5/13	MAKE	SUMITOMO	MODEL	SH120-3
SERIAL	120Z3-1886			STAMP	120Z3-1886
HR METER	UNKNOWN		HR	YEAR	2002 YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	500G

ENGINE : MODEL 4BG1 S/N	
Oil leakage	FAIR · Attn
Blow-By	FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn
Oil	FAIR · Attn
Exhaust Color	FAIR · Attn
US EPA	YES · NO
MAIN PUMP	
Sound	FAIR · Attn
Oil leakage	FAIR · Attn
Power	FAIR · Attn
COOLING SYSTEM	
Radiator	FAIR · Attn
Oil Cooler	FAIR · Attn
OPERATING SYSTEM	
Swing	FAIR · Attn ガタあり SWING: LOOSE
Travel	FAIR · Attn
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN · FAIR · DIRTY
Operator's Seat	FAIR · Attn ガタあり LOOSE
Glasses	FAIR · Attn
AirCon	A/C · H/C · H only · C only · None
BOOM / ARM / BKT	
Boom	FAIR · Attn
Boom Cylinder	FAIR · Attn
Arm	FAIR · Attn
Arm Cylinder	FAIR · Attn
BKT	FAIR · Attn *1
BKT Cylinder	FAIR · Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
COMMENT	
BKT	STD / SLOPE / NARROW / SKELETON (OTHER)
Lever	LONG · WRIST
Multi	MULTI · 2 · NO
ARM-CRANE	YES · NO
BLADE	YES · NO
OFFSET	YES · NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · NO Breaker only · Multi
COMMENT	
アタッチメント: チューリップバケット ATTACHMENT: ORANGE PEEL GRAPPLE	
MAKE: MARUJUN DG120-020708-008	
右サイドカバー変形あり RIGHT SIDE COVER: DEFORMED	
ハイCAB HIGH CAB	
メーターパネル動作しない、表示しない INDICATOR PANEL: MALFUNCTION	
HRメーター不良 HR METER: MALFUNCTION	
*1 ツメ1本しか動かない、ローアイドルだと動作しない、 開いたまま保持不可、レバー中立で戻る	
*1 ONE OF FORKS: ONLY ABLE TO WORK, UNABLE TO OPERATE WITH LOW IDLING, FORK: UNABLE TO KEEP SPREAD POSITION, LEVER AT NEUTRAL POSITION: CLOSING FORK	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。