## INSPECTION SHEET 検品書 CARRY DUMP キャリーダンプ

INSPECTIO	2025/3/19 MAKE				MAKE	N	IOROOKA		MC	DEL	MST-800VD			
SERIAL	81270				0		-	STAMP				81270		
HR METER	2083 HF			HR	Odometer				ŀ	km	YEAR			YR
CAB/CNP	ROPS CA	AB (	CAB	ROP	S CNP	/ CNP	/ NONE	SHOE		600F	₹	TIRE		
ENGINE: MODEL S/N								MAIN FRAME						
Oil leakage	FAIR · Attn							MAIN FL	ΑМЕ	FAIR	■ Attn			
Blow-By	FAIR · Attn	A LIT	TLE · M	IIDDL	Е•	SEVERE		VESSEL						
Sound	FAIR · Attn							VESSE	L	FAIR	<ul><li>Attn</li></ul>	*1		
Oil	FAIR · Attn							REAR GATE	TYP€	N	ORMAI	L-	-GATE (FLAT)	
Exhaust Color	FAIR · Attn							REAR GA	ATE	FAIR	<ul><li>Attn</li></ul>			
US EPA	YES · NO					UNDERCARRIAGE: See Photos. 写真参照								
OPERATION PUMP								RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 4						
Sound	FAIR · Attn							TIRE WE	AR	FA	JR • W	ORN • UI	NEVEN WEAR	
Oil leakage	FAIR · Attn							COMMENT	-					
Power	FAIR · Attn							*1 左側リフト	シリンタ	ダー傷	あり LE	FT LIFT C	YLINDER: SCRA	TCHED
COOLING	SYSTEM													
Radiator	FAIR · Attn													
Oil Cooler	FAIR · Attn													
TRANSMISSION & TRAVEL														
T/M TYPE	PS) · DD				No. OF	GEARS 2	GEARS							
Transmission	FAIR · Attn													
Travel	FAIR · Attn													
Swing	FAIR · Attn													
Articulate	FAIR · Attn													
FOOT BRAKE	FAIR · Attn													
PARKING BRAKE	FAIR · Attn													
INTERIOR See Photos. 写真参照														
INTERIOR COND.	CLEAN	>	FAIR	•	DIF	RTY								
Operator's Seat	FAIR · Attn													
Glasses	FAIR · Attn													
AirCon	A/C ·	H/C	· (н	only	• C	only •	None	RUST of BODY	(5: NONE	, 4: A L	ITTLE, 3: N	MIDDLE, 2: MU	CH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine. この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。