

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/4/7	MAKE	KOBELCO	MODEL	SK950DLC
SERIAL	LV01-00104			STAMP	LV01-00104
HR METER	9536	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	650G

ENGINE : MODEL		S/N
Oil leakage	FAIR	Attn
Blow-By	FAIR	Attn
Sound	FAIR	Attn
Oil	FAIR	Attn
Exhaust Color	FAIR	Attn
US EPA	YES	NO
MAIN PUMP		
Sound	FAIR	Attn
Oil leakage	FAIR	Attn
Power	FAIR	Attn
COOLING SYSTEM		
Radiator	FAIR	Attn
Oil Cooler	FAIR	Attn
OPERATING SYSTEM		
Swing	FAIR	Attn
Travel	FAIR	Attn
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN	FAIR
Operator's Seat	FAIR	Attn
Glasses	FAIR	Attn
AirCon	A/C	H/C H only C only None
BOOM / ARM / BKT		
Boom	FAIR	Attn
Boom Cylinder	FAIR	Attn
Arm	FAIR	Attn
Arm Cylinder	FAIR	Attn
BKT	FAIR	Attn
BKT Cylinder	FAIR	Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
BKT (STD / SLOPE / NARROW / SKELETON / OTHER ())	
Lever	LONG WRIST
Multi	MULTI 2 NO
ARM-CRANE	YES NO
BLADE	YES NO
OFFSET	YES NO
OFFSET Cylinder	FAIR Attn
Piping	YES NO Breaker only Multi
COMMENT	
油圧を掛けている間P1ポンプ圧力センサ表示あり	
WARNING DISPLAY FOR P1 PUMP PRESSURE SENSOR	
DURING SUPPLYING SOME HYDRAULIC PRESSURE	
転倒危険！表示消えない	
WARNING DISPLAY FOR FALLING DOWN: UNABLE TO GO OUT	
バックカメラ不良 BACK MONITOR: MALFUNCTION	
A/Cユニット電源入らない A/C UNIT: UNABLE TO TURN ON	
付属品:ジャッキ、台座 JACKS & FIXING STAND AS SPARE	
*1 左右油漏れ大(オークション後修理予定)	
*1 CYLINDERS: SEVERE OIL LEAKING (REPAIRING AFTER THE AUCTION)	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。