

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/3/25	MAKE	KATO	MODEL	KR-25H-V8
SERIAL No.	PLATE : 6710250		STAMP : KRC011-0250		
HR METER	12635	HR	Odometer	63215	km
TIRE SIZE	385/95R25		YEAR	YR	

ENGINE : MODEL		S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
OPERATION PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	
COOLING SYSTEM		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	
OPERATING SYSTEM		
Computer	OK · NG	
Swing	FAIR · Attn	
Travel	FAIR · Attn	
TRANSMISSION		
Transmission	FAIR · Attn	
No. OF GEARS	4 GEARS	
4WD	4WD · 6WD	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · DIRTY	
Operator's Seat	FAIR · Attn	
Glasses	FAIR · Attn	F傷あり WINDSHIELD: SCRATCHED
AirCon	A/C · H/C · H only · C only · None	
COMMENT		

BOOM						
No. of Section	4 SECTIONS					
CRACK/ENFORCEMENT	(FAIR)	▪ Attn				
DERRICKING CYL.	(FAIR)	▪ Attn				
EXTENSION CYL.	(FAIR)	▪ Attn				
JIB	(YES)	▪ NO				
JIB TYPE	STD	▪ (PWR)				
MAIN & SUB WIRE	(YES)	▪ NO				
HOOK	25t, BALL					
UNDERCARRIAGE : See Photos. 写真参照						
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3					
TIRE WEAR	(FAIR) ▪ WORN ▪ UNEVEN WEAR					
COMMENT 						
OUTRIGGERS						
OUTRIGGERS	(X)	▪ H				
OUTRIGGERS COND.	(FAIR)	▪ Attn				
Oil leakage (JACK CYL.)	FRONT	L	▪ R	REAR	L · R	
Oil leakage (SLIDE CYL.)	FRONT	L	▪ R	REAR	L · R	
COMMENT 						
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)						3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。