

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/3/25	MAKE	KOBELCO	MODEL	SK135SR-3F
SERIAL	YY07-28592			STAMP	YY07-28592
HR METER	7518	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	600G PADS

ENGINE : MODEL		S/N
Oil leakage	FAIR • Attn	
Blow-By	FAIR • Attn	A LITTLE • MIDDLE • SEVERE
Sound	FAIR • Attn	
Oil	FAIR • Attn	
Exhaust Color	FAIR • Attn	
US EPA	YES • NO	

MAIN PUMP		
Sound	FAIR • Attn	
Oil leakage	FAIR • Attn	
Power	FAIR • Attn	

COOLING SYSTEM		
Radiator	FAIR • Attn	
Oil Cooler	FAIR • Attn	

OPERATING SYSTEM		
Swing	FAIR • Attn	
Travel	FAIR • Attn	

INTERIOR		See Photos. 写真参照
INTERIOR COND.	CLEAN • FAIR • DIRTY	
Operator's Seat	FAIR • Attn	破れあり CUT
Glasses	FAIR • Attn	*1
AirCon	A/C • H/C • H only • C only • None	

BOOM / ARM / BKT		
Boom	FAIR • Attn	補強跡あり REINFORCED
Boom Cylinder	FAIR • Attn	
Arm	FAIR • Attn	補強跡あり REINFORCED
Arm Cylinder	FAIR • Attn	
BKT	FAIR • Attn	
BKT Cylinder	FAIR • Attn	

UNDERCARRIAGE :		See Photos. 写真参照
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4	

COMMENT		

BKT	STD / SLOPE / NARROW / SKELETON / OTHER ()	
Lever	LONG • WRIST	
Multi	MULTI • 2 • NO	
ARM-CRANE	YES • NO	
BLADE	YES • NO	
OFFSET	YES • NO	
OFFSET Cylinder	FAIR • Attn	
Piping	YES • NO	Breaker only • Multi 5 *2

COMMENT		
左サイドカバーラッチ不良 LEFT SIDE COVER LATCH: MALFUNCTION		
*1 ドア下アクリル板割れあり		
*1 LOWER DOOR GLASS: ACRYLIC BOARD (CRACKED)		
*2 油圧ホースブーム背中側1本繋がっていない		
*2 SOME HOSE AROUND LOWER PART OF BOOM: NOT ATTACHED		

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4	
--	---	--

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。