

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/3/25	MAKE	TADANO	MODEL	TR-250M-6
SERIAL No.	PLATE : FB2404		STAMP : TR255-0932		
HR METER	ERROR		HR	Odometer	ERROR km
TIRE SIZE	385/95R25		YEAR	YR	

ENGINE : MODEL		S/N	
Oil leakage	FAIR · Attn		
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR · Attn		
Oil	FAIR · Attn		
Exhaust Color	FAIR · Attn		
OPERATION PUMP			
Sound	FAIR · Attn		
Oil leakage	FAIR · Attn		
Power	FAIR · Attn		
COOLING SYSTEM			
Radiator	FAIR · Attn		
Oil Cooler	FAIR · Attn		
OPERATING SYSTEM			
Computer	OK · NG		
Swing	FAIR · Attn		
Travel	FAIR · Attn		
TRANSMISSION			
Transmission	FAIR · Attn		
No. OF GEARS	4	GEARS	
4WD	4WD · 6WD		
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN · FAIR · DIRTY		
Operator's Seat	FAIR · Attn		
Glasses	FAIR · Attn	*1	
AirCon	A/C · H/C · H only · C only · None		
COMMENT			

BOOM						
No. of Section		4		SECTIONS		
CRACK/ENFORCEMENT	FAIR	▪ Attn				
DERRICKING CYL.	FAIR	▪ Attn		油漏れあり OIL LEAKING		
EXTENSION CYL.	FAIR	▪ Attn				
JIB	YES	▪ NO				
JIB TYPE	STD	▪ PWR				
MAIN & SUB WIRE	YES	▪ NO				
HOOK	25t, BALL					
UNDERCARRIAGE : See Photos. 写真参照						
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)						1
TIRE WEAR	FAIR ▪ WORN ▪ UNEVEN WEAR					
COMMENT						
OUTRIGGERS						
OUTRIGGERS	X	▪ H				
OUTRIGGERS COND.	FAIR	▪ Attn				
Oil leakage (JACK CYL.)	FRONT	L	▪ R	REAR	L ▪ R	
Oil leakage (SLIDE CYL.)	FRONT	L	▪ R	REAR	L ▪ R	
COMMENT						
エアー漏れ大 MUCH AIR LEAKING						
リターダ油漏れあり RETARDER: OIL LEAKING						
ブーム縮める時ビビリ音あり						
RATTLING NOISES DURING SHRINKING THE BOOM						
*1 パワーウインドウ故障あり POWER WINDOWS: MALFUNCTION						
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)						1

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。