

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2025/3/4	MAKE	KOMATSU	MODEL	D20PLL-7E
SERIAL	62520			STAMP	D20PL7E-62520
HR METER	4311	HR	SHOE	1050LGP	YEAR 1996 YR
BLADE	STRAIGHT ST/TILT PAT / ANGLE / OTHER			CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE

<table style="width: 100%;"> <tr> <td style="width: 50%;">ENGINE : MODEL</td> <td style="width: 50%;">S/N</td> </tr> <tr> <td>Oil leakage FAIR · Attn</td> <td></td> </tr> <tr> <td>Blow-By FAIR · Attn</td> <td>A LITTLE · MIDDLE · SEVERE</td> </tr> <tr> <td>Sound FAIR · Attn</td> <td></td> </tr> <tr> <td>Oil FAIR · Attn</td> <td></td> </tr> <tr> <td>Exhaust Color FAIR · Attn</td> <td></td> </tr> <tr> <td>US EPA YES · NO</td> <td></td> </tr> <tr> <td colspan="2">OPERATION PUMP</td> </tr> <tr> <td>Sound FAIR · Attn</td> <td></td> </tr> <tr> <td>Oil leakage FAIR · Attn</td> <td></td> </tr> <tr> <td>Power FAIR · Attn</td> <td></td> </tr> <tr> <td colspan="2">COOLING SYSTEM</td> </tr> <tr> <td>Radiator FAIR · Attn</td> <td></td> </tr> <tr> <td>Oil Cooler FAIR · Attn</td> <td></td> </tr> <tr> <td colspan="2">TRANSMISSION & TRAVEL</td> </tr> <tr> <td>T/M TYPE PS · DD</td> <td>DIFF. STEERING YES · NO</td> </tr> <tr> <td>Transmission FAIR · Attn</td> <td></td> </tr> <tr> <td>Travel FAIR · Attn</td> <td></td> </tr> <tr> <td colspan="2">INTERIOR See Photos. 写真参照</td> </tr> <tr> <td>Operator's Seat FAIR · Attn</td> <td></td> </tr> <tr> <td>Inside Cover FAIR · Attn</td> <td></td> </tr> <tr> <td>Glasses FAIR · Attn</td> <td>Rガラス割れあり REAR GLASS: CRACKED</td> </tr> <tr> <td>AirCon A/C · H/C · H only · C only · None</td> <td></td> </tr> <tr> <td colspan="2">BLADE & CYLINDERS</td> </tr> <tr> <td>BLADE FAIR · Attn</td> <td></td> </tr> <tr> <td>CYLD.(R) FAIR · Attn</td> <td></td> </tr> <tr> <td>CYLD.(L) FAIR · Attn</td> <td></td> </tr> <tr> <td>TILT CYLD FAIR · Attn</td> <td></td> </tr> <tr> <td>ANGLE CYLD FAIR · Attn</td> <td></td> </tr> </table>	ENGINE : MODEL	S/N	Oil leakage FAIR · Attn		Blow-By FAIR · Attn	A LITTLE · MIDDLE · SEVERE	Sound FAIR · Attn		Oil FAIR · Attn		Exhaust Color FAIR · Attn		US EPA YES · NO		OPERATION PUMP		Sound FAIR · Attn		Oil leakage FAIR · Attn		Power FAIR · Attn		COOLING SYSTEM		Radiator FAIR · Attn		Oil Cooler FAIR · Attn		TRANSMISSION & TRAVEL		T/M TYPE PS · DD	DIFF. STEERING YES · NO	Transmission FAIR · Attn		Travel FAIR · Attn		INTERIOR See Photos. 写真参照		Operator's Seat FAIR · Attn		Inside Cover FAIR · Attn		Glasses FAIR · Attn	Rガラス割れあり REAR GLASS: CRACKED	AirCon A/C · H/C · H only · C only · None		BLADE & CYLINDERS		BLADE FAIR · Attn		CYLD.(R) FAIR · Attn		CYLD.(L) FAIR · Attn		TILT CYLD FAIR · Attn		ANGLE CYLD FAIR · Attn		<table style="width: 100%;"> <tr> <td colspan="2">UNDERCARRIAGE See Photos. 写真参照</td> </tr> <tr> <td>RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</td> <td style="text-align: center;">3</td> </tr> <tr> <td colspan="2">COMMENT</td> </tr> <tr><td colspan="2" style="height: 40px;"></td></tr> <tr><td colspan="2" style="height: 40px;"></td></tr> <tr><td colspan="2" style="height: 40px;"></td></tr> <tr><td colspan="2" style="height: 40px;"></td></tr> <tr> <td>Ripper</td> <td>MULTI · S/S Shanks PCS</td> </tr> <tr> <td>Ripper CYLD.</td> <td>FAIR · Attn</td> </tr> <tr> <td>EQUALIZER BAR</td> <td>FAIR · Attn</td> </tr> <tr> <td colspan="2">COMMENT</td> </tr> <tr> <td colspan="2">トプコンフルオート 動作未確認</td> </tr> <tr> <td colspan="2">TOPCON FULL-AUTO : NOT CHECKED</td> </tr> <tr><td colspan="2" style="height: 40px;"></td></tr> <tr><td colspan="2" style="height: 40px;"></td></tr> <tr><td colspan="2" style="height: 40px;"></td></tr> <tr><td colspan="2" style="height: 40px;"></td></tr> <tr><td colspan="2" style="height: 40px;"></td></tr> <tr><td colspan="2" style="height: 40px;"></td></tr> <tr><td colspan="2" style="height: 40px;"></td></tr> <tr><td colspan="2" style="height: 40px;"></td></tr> <tr><td colspan="2" style="height: 40px;"></td></tr> <tr> <td colspan="2">RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</td> </tr> <tr> <td colspan="2" style="text-align: center;">3</td> </tr> </table>	UNDERCARRIAGE See Photos. 写真参照		RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3	COMMENT										Ripper	MULTI · S/S Shanks PCS	Ripper CYLD.	FAIR · Attn	EQUALIZER BAR	FAIR · Attn	COMMENT		トプコンフルオート 動作未確認		TOPCON FULL-AUTO : NOT CHECKED																				RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3	
ENGINE : MODEL	S/N																																																																																																										
Oil leakage FAIR · Attn																																																																																																											
Blow-By FAIR · Attn	A LITTLE · MIDDLE · SEVERE																																																																																																										
Sound FAIR · Attn																																																																																																											
Oil FAIR · Attn																																																																																																											
Exhaust Color FAIR · Attn																																																																																																											
US EPA YES · NO																																																																																																											
OPERATION PUMP																																																																																																											
Sound FAIR · Attn																																																																																																											
Oil leakage FAIR · Attn																																																																																																											
Power FAIR · Attn																																																																																																											
COOLING SYSTEM																																																																																																											
Radiator FAIR · Attn																																																																																																											
Oil Cooler FAIR · Attn																																																																																																											
TRANSMISSION & TRAVEL																																																																																																											
T/M TYPE PS · DD	DIFF. STEERING YES · NO																																																																																																										
Transmission FAIR · Attn																																																																																																											
Travel FAIR · Attn																																																																																																											
INTERIOR See Photos. 写真参照																																																																																																											
Operator's Seat FAIR · Attn																																																																																																											
Inside Cover FAIR · Attn																																																																																																											
Glasses FAIR · Attn	Rガラス割れあり REAR GLASS: CRACKED																																																																																																										
AirCon A/C · H/C · H only · C only · None																																																																																																											
BLADE & CYLINDERS																																																																																																											
BLADE FAIR · Attn																																																																																																											
CYLD.(R) FAIR · Attn																																																																																																											
CYLD.(L) FAIR · Attn																																																																																																											
TILT CYLD FAIR · Attn																																																																																																											
ANGLE CYLD FAIR · Attn																																																																																																											
UNDERCARRIAGE See Photos. 写真参照																																																																																																											
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3																																																																																																										
COMMENT																																																																																																											
Ripper	MULTI · S/S Shanks PCS																																																																																																										
Ripper CYLD.	FAIR · Attn																																																																																																										
EQUALIZER BAR	FAIR · Attn																																																																																																										
COMMENT																																																																																																											
トプコンフルオート 動作未確認																																																																																																											
TOPCON FULL-AUTO : NOT CHECKED																																																																																																											
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)																																																																																																											
3																																																																																																											

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。