

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/3/26	MAKE	KOMATSU	MODEL	PC200-8E0
SERIAL	1143		STAMP	UNREADABLE	
HR METER	ERROR		HR	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	610FLAT	

ENGINE : MODEL		S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · NO	
MAIN PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	
COOLING SYSTEM		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	
OPERATING SYSTEM		
Swing	FAIR · Attn	
Travel	FAIR · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · DIRTY	
Operator's Seat	FAIR · Attn	破れあり CUTS
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · None	
BOOM / ARM / BKT		
Boom	FAIR · Attn	
Boom Cylinder	FAIR · Attn	
Arm	FAIR · Attn	
Arm Cylinder	FAIR · Attn	
BKT	FAIR · Attn	
BKT Cylinder	FAIR · Attn	

UNDERCARRIAGE :						See Photos.	写真参照
RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)							3
COMMENT							
BKT	(STD / SLOPE / NARROW / SKELETON / OTHER()						
Lever	LONG ▪ (WRIST)						
Multi	(MULTI) ▪ 2 ▪ NO						
ARM-CRANE	YES ▪ (NO)						
BLADE	YES ▪ (NO)						
OFFSET	YES ▪ (NO)						
OFFSET Cylinder	FAIR ▪ Attn						
Piping	(YES) ▪ NO	Breaker only	(Multi)				
COMMENT							
E09が一度だけ表示され旋回不可になった、E/G再始動で解消 UNABLE TO SWING DURING "E09" ERROR DISPLAYING (ABLE TO SOLVE THE TROUBLE BY RESTARTING THE ENGINE, THE ERROR: NO LONGER DISPLAYED) 							
RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)							3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。