

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/3/25	MAKE	KOBELCO	MODEL	LK300
SERIAL	RL-04002			STAMP	LK302-4002
HR METER	4654	HR	Odometer	—	km
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	16.9-24

ENGINE : MODEL		S/N
Oil leakage	☒ FAIR · Attn	油汚れあり OIL STAINS
Blow-By	☒ FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	☒ FAIR · Attn	
Oil	☒ FAIR · Attn	
Exhaust Color	☒ FAIR · Attn	
US EPA	YES · ☒ NO	
OPERATION PUMP		
Sound	☒ FAIR · Attn	
Oil leakage	☒ FAIR · Attn	
Power	☒ FAIR · Attn	
COOLING SYSTEM		
Radiator	☒ FAIR · Attn	
Oil Cooler	☒ FAIR · Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	☒ PS · DD	
Transmission	☒ FAIR · Attn	
Travel	☒ FAIR · Attn	
FOOT BRAKE	☒ FAIR · Attn	
PARKING BRAKE	☒ FAIR · ☒ Attn	効き甘い BRAKE: LOOSE
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · ☒ FAIR ·	DIRTY
Operator's Seat	☒ FAIR · Attn	穴あり HOLE
Glasses	☒ FAIR · Attn	
AirCon	A/C · H/C · ☒ H only · C only · None	
FRONT & CYLINDERS		
Arm	☒ FAIR · Attn	
Bell crank	☒ FAIR · Attn	
Bucket	☒ FAIR · ☒ Attn	*1
Articulate	☒ FAIR · Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR	☒ FAIR · ☐ WORN · ☐ UNEVEN WEAR
COMMENT	
STEERING TYPE ☒ WHEEL STEERING / ☐ COMMAND STEERING / ☐ LEVER STEERING	
RIDE CONTROL	YES · ☒ NO
ATTACHMENTS	
STD BKT	☒ YES · ☐ OTHER
BLADE	YES · ☒ NO Piping for Tilt ☒ YES · ☐ NO
COMMENT	
右サイドカバー変形あり、閉まらない RIGHT SIDE COVER: DEFORMED, UNABLE TO SHUT *1 シリンダー油漏れ、ピンガタあり CYLINDER: OIL LEAKING, PIN: LOOSE	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
2	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。