

INSPECTION SHEET 検品書
GENERATOR / COMPRESSOR / WELDER 発電機・コンプレッサー・ウェルダー

INSPECTION DATE	2025/3/26	CATEGORY	GENERATOR / COMPRESSOR / WELDER		
MAKE	DENYO		MODEL	DCA-125LSI	
SERIAL	3862065		STAMP	NOT FOUND	
HR METER	368	HR	TIRE SIZE	YEAR	YR

ENGINE :	MODEL	4HK1	S/N	497378	
Oil leakage	<input checked="" type="radio"/> FAIR ▪ Attn		Oil	<input checked="" type="radio"/> FAIR ▪ Attn	
Blow-By	<input checked="" type="radio"/> FAIR ▪ Attn	A LITTLE ▪ MIDDLE ▪ SEVERE	Exhaust Color	<input checked="" type="radio"/> FAIR ▪ Attn	
Sound	<input checked="" type="radio"/> FAIR ▪ Attn		Radiator	<input checked="" type="radio"/> FAIR ▪ Attn	

GENERATOR					
RATED POWER	100 / 125	KVA	Leaking Breaker Condition	<input checked="" type="radio"/> FAIR ▪ Attn	
RATED AMPERE	289, 144 / 328, 164	A	Insulation Condition	<input checked="" type="radio"/> FAIR ▪ Attn	
Output Terminal	<input checked="" type="radio"/> FAIR ▪ Attn				

COMPRESSOR					
RATED PRESSURE		Mpa Kgf/cm2	Unload Condition	<input type="radio"/> FAIR ▪ Attn	
RATED AIR FLOW		m3/min	Receiver Tank Condition	<input type="radio"/> FAIR ▪ Attn	
Compressor Oil Leak	<input type="radio"/> FAIR ▪ Attn		Safety Valve Condition	<input type="radio"/> FAIR ▪ Attn	

CONDITION	<input checked="" type="radio"/> FAIR ▪ Attn	

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4	TIRE WEAR	FAIR ▪ WORN ▪ UNEVEN WEAR
--	---	-----------	---------------------------

COMMENTS <div style="border-bottom: 1px dotted black; height: 15px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 15px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 15px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 15px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 15px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 15px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 15px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 15px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 15px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 15px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 15px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 15px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 15px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 15px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 15px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 15px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 15px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 15px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 15px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 15px; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; height: 15px; margin-bottom: 5px;"></div>

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。