

INSPECTION SHEET 検品書
CARRY DUMP キャリーダンプ

INSPECTION DATE	2025/3/19	MAKE	MOROOKA	MODEL	MST-1100		
SERIAL	111125			STAMP	111125		
HR METER	9418	HR	Odometer	km	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	700R	TIRE	

ENGINE :		MODEL		S/N	
Oil leakage	FAIR	Attn	ヘッドカバーにじみあり HEAD COVER: OIL OOZING		
Blow-By	FAIR	Attn	A LITTLE ・ MIDDLE ・ SEVERE		
Sound	FAIR	Attn			
Oil	FAIR	Attn			
Exhaust Color	FAIR	Attn	白煙あり WHITE FUMES		
US EPA	YES	NO			
OPERATION PUMP					
Sound	FAIR	Attn			
Oil leakage	FAIR	Attn			
Power	FAIR	Attn			
COOLING SYSTEM					
Radiator	FAIR	Attn			
Oil Cooler	FAIR	Attn			
TRANSMISSION & TRAVEL					
T/M TYPE	PS	DD		No. OF GEARS	- GEARS
Transmission	FAIR	Attn			
Travel	FAIR	Attn			
Swing	FAIR	Attn			
Articulate	FAIR	Attn			
FOOT BRAKE	FAIR	Attn			
PARKING BRAKE	FAIR	Attn			
INTERIOR See Photos. 写真参照					
INTERIOR COND.	CLEAN	FAIR	DIRTY		
Operator's Seat	FAIR	Attn	穴、破れあり HOLE, CUTS		
Glasses	FAIR	Attn			
AirCon	A/C	H/C	H only	C only	None

MAIN FRAME					
MAIN FLAME		(FAIR)	▪ Attn	サビあり RUSTY	
VESSEL					
VESSEL		FAIR	▪ (Attn)	*1	
REAR GATE TYPE		(NORMAL)			▪ L-GATE (FLAT)
REAR GATE		(FAIR)	▪ Attn	サビ、溶接あり RUSTY, WELDED	
UNDERCARRIAGE: See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					2
TIRE WEAR		FAIR ▪ WORN ▪ UNEVEN WEAR			
COMMENT					
ヒーター故障あり HEATER: MALFUNCTION					
E/Gとポンプの合わせにじみあり					
ATTACHING PART BETWEEN ENGINE & PUMP: OIL OOZING					
左トラックローラー欠 SOME LEFT TRACK ROLLERS: MISSING					
ドア欠 DOOR: MISSING					
*1 サビ、穴、左シリンダー、ホースにじみあり					
*1 RUSTY, HUGE HOLE, LEFT CYLINDER & HOSE: OIL OOZING					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					1

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。