

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2025/3/27	MAKE	CAT	MODEL	D6TLGP
SERIAL	CAT00D6TCJRW00258			STAMP	CAT00D6TCJRW00258
HR METER	10722	HR	SHOE	1000LGP	YEAR YR
BLADE	STRAIGHT / <u>ST/TILT</u> / PAT / ANGLE / OTHER			CAB/CNP	ROPS CAB / <u>CAB</u> / ROPS CNP / CNP / NONE

<table style="width: 100%;"> <tr> <td style="width: 50%;">ENGINE : MODEL</td> <td style="width: 50%;">S/N</td> </tr> <tr> <td>Oil leakage</td> <td><u>FAIR</u> • Attn</td> </tr> <tr> <td>Blow-By</td> <td><u>FAIR</u> • Attn A LITTLE • MIDDLE • SEVERE</td> </tr> <tr> <td>Sound</td> <td><u>FAIR</u> • <u>Attn</u> 異音あり NOISES</td> </tr> <tr> <td>Oil</td> <td><u>FAIR</u> • Attn</td> </tr> <tr> <td>Exhaust Color</td> <td><u>FAIR</u> • Attn</td> </tr> <tr> <td>US EPA</td> <td>YES • <u>NO</u></td> </tr> <tr> <td colspan="2">OPERATION PUMP</td> </tr> <tr> <td>Sound</td> <td><u>FAIR</u> • Attn</td> </tr> <tr> <td>Oil leakage</td> <td><u>FAIR</u> • Attn</td> </tr> <tr> <td>Power</td> <td><u>FAIR</u> • Attn</td> </tr> <tr> <td colspan="2">COOLING SYSTEM</td> </tr> <tr> <td>Radiator</td> <td><u>FAIR</u> • Attn</td> </tr> <tr> <td>Oil Cooler</td> <td><u>FAIR</u> • Attn</td> </tr> <tr> <td colspan="2">TRANSMISSION & TRAVEL</td> </tr> <tr> <td>T/M TYPE</td> <td><u>PS</u> • DD DIFF. STEERING <u>YES</u> • NO</td> </tr> <tr> <td>Transmission</td> <td><u>FAIR</u> • Attn</td> </tr> <tr> <td>Travel</td> <td><u>FAIR</u> • Attn</td> </tr> <tr> <td colspan="2">INTERIOR See Photos. 写真参照</td> </tr> <tr> <td>INTERIOR COND.</td> <td>CLEAN • <u>FAIR</u> • DIRTY</td> </tr> <tr> <td>Operator's Seat</td> <td><u>FAIR</u> • Attn</td> </tr> <tr> <td>Glasses</td> <td><u>FAIR</u> • Attn</td> </tr> <tr> <td>AirCon</td> <td><u>A/C</u> • H/C • H only • C only • None</td> </tr> <tr> <td colspan="2">BLADE & CYLINDERS</td> </tr> <tr> <td>BLADE</td> <td><u>FAIR</u> • Attn</td> </tr> <tr> <td>CYLD.(R)</td> <td><u>FAIR</u> • Attn</td> </tr> <tr> <td>CYLD.(L)</td> <td><u>FAIR</u> • Attn</td> </tr> <tr> <td>TILT CYLD</td> <td><u>FAIR</u> • Attn</td> </tr> <tr> <td>ANGLE CYLD</td> <td><u>FAIR</u> • Attn</td> </tr> </table>	ENGINE : MODEL	S/N	Oil leakage	<u>FAIR</u> • Attn	Blow-By	<u>FAIR</u> • Attn A LITTLE • MIDDLE • SEVERE	Sound	<u>FAIR</u> • <u>Attn</u> 異音あり NOISES	Oil	<u>FAIR</u> • Attn	Exhaust Color	<u>FAIR</u> • Attn	US EPA	YES • <u>NO</u>	OPERATION PUMP		Sound	<u>FAIR</u> • Attn	Oil leakage	<u>FAIR</u> • Attn	Power	<u>FAIR</u> • Attn	COOLING SYSTEM		Radiator	<u>FAIR</u> • Attn	Oil Cooler	<u>FAIR</u> • Attn	TRANSMISSION & TRAVEL		T/M TYPE	<u>PS</u> • DD DIFF. STEERING <u>YES</u> • NO	Transmission	<u>FAIR</u> • Attn	Travel	<u>FAIR</u> • Attn	INTERIOR See Photos. 写真参照		INTERIOR COND.	CLEAN • <u>FAIR</u> • DIRTY	Operator's Seat	<u>FAIR</u> • Attn	Glasses	<u>FAIR</u> • Attn	AirCon	<u>A/C</u> • H/C • H only • C only • None	BLADE & CYLINDERS		BLADE	<u>FAIR</u> • Attn	CYLD.(R)	<u>FAIR</u> • Attn	CYLD.(L)	<u>FAIR</u> • Attn	TILT CYLD	<u>FAIR</u> • Attn	ANGLE CYLD	<u>FAIR</u> • Attn	<table style="width: 100%;"> <tr> <td colspan="2">UNDERCARRIAGE See Photos. 写真参照</td> </tr> <tr> <td colspan="2">RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 4</td> </tr> <tr> <td colspan="2">COMMENT</td> </tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr> <td>Ripper</td> <td>MULTI • S/S Shanks PCS</td> </tr> <tr> <td>Ripper CYLD.</td> <td><u>FAIR</u> • Attn</td> </tr> <tr> <td>EQUALIZER BAR</td> <td><u>FAIR</u> • Attn</td> </tr> <tr> <td colspan="2">COMMENT</td> </tr> <tr> <td colspan="2">オルタネータ未充電警告あり(E179-2)</td> </tr> <tr> <td colspan="2">"E179-2" ERROR DISPLAY FOR UNCHARGED ALTERNATOR</td> </tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr> <td colspan="2">RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 4</td> </tr> </table>	UNDERCARRIAGE See Photos. 写真参照		RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 4		COMMENT												Ripper	MULTI • S/S Shanks PCS	Ripper CYLD.	<u>FAIR</u> • Attn	EQUALIZER BAR	<u>FAIR</u> • Attn	COMMENT		オルタネータ未充電警告あり(E179-2)		"E179-2" ERROR DISPLAY FOR UNCHARGED ALTERNATOR																								RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 4	
ENGINE : MODEL	S/N																																																																																																														
Oil leakage	<u>FAIR</u> • Attn																																																																																																														
Blow-By	<u>FAIR</u> • Attn A LITTLE • MIDDLE • SEVERE																																																																																																														
Sound	<u>FAIR</u> • <u>Attn</u> 異音あり NOISES																																																																																																														
Oil	<u>FAIR</u> • Attn																																																																																																														
Exhaust Color	<u>FAIR</u> • Attn																																																																																																														
US EPA	YES • <u>NO</u>																																																																																																														
OPERATION PUMP																																																																																																															
Sound	<u>FAIR</u> • Attn																																																																																																														
Oil leakage	<u>FAIR</u> • Attn																																																																																																														
Power	<u>FAIR</u> • Attn																																																																																																														
COOLING SYSTEM																																																																																																															
Radiator	<u>FAIR</u> • Attn																																																																																																														
Oil Cooler	<u>FAIR</u> • Attn																																																																																																														
TRANSMISSION & TRAVEL																																																																																																															
T/M TYPE	<u>PS</u> • DD DIFF. STEERING <u>YES</u> • NO																																																																																																														
Transmission	<u>FAIR</u> • Attn																																																																																																														
Travel	<u>FAIR</u> • Attn																																																																																																														
INTERIOR See Photos. 写真参照																																																																																																															
INTERIOR COND.	CLEAN • <u>FAIR</u> • DIRTY																																																																																																														
Operator's Seat	<u>FAIR</u> • Attn																																																																																																														
Glasses	<u>FAIR</u> • Attn																																																																																																														
AirCon	<u>A/C</u> • H/C • H only • C only • None																																																																																																														
BLADE & CYLINDERS																																																																																																															
BLADE	<u>FAIR</u> • Attn																																																																																																														
CYLD.(R)	<u>FAIR</u> • Attn																																																																																																														
CYLD.(L)	<u>FAIR</u> • Attn																																																																																																														
TILT CYLD	<u>FAIR</u> • Attn																																																																																																														
ANGLE CYLD	<u>FAIR</u> • Attn																																																																																																														
UNDERCARRIAGE See Photos. 写真参照																																																																																																															
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 4																																																																																																															
COMMENT																																																																																																															
Ripper	MULTI • S/S Shanks PCS																																																																																																														
Ripper CYLD.	<u>FAIR</u> • Attn																																																																																																														
EQUALIZER BAR	<u>FAIR</u> • Attn																																																																																																														
COMMENT																																																																																																															
オルタネータ未充電警告あり(E179-2)																																																																																																															
"E179-2" ERROR DISPLAY FOR UNCHARGED ALTERNATOR																																																																																																															
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 4																																																																																																															

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。