

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/6/3	MAKE	KOMATSU	MODEL	HB205-2
SERIAL	50483		STAMP	KMT HB004JEC050483	
HR METER	16824	HR	YEAR	2014	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

ENGINE : MODEL		S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · NO	
MAIN PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	
COOLING SYSTEM		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	目詰まり多い MUCH CLOGGED
OPERATING SYSTEM		
Swing	FAIR · Attn	
Travel	FAIR · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · DIRTY	
Operator's Seat	FAIR · Attn	*1
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · None	
BOOM / ARM / BKT		
Boom	FAIR · Attn	パッチあり PATCHED
Boom Cylinder	FAIR · Attn	左右油漏れ小 CYLINDER: OIL LEAKING
Arm	FAIR · Attn	
Arm Cylinder	FAIR · Attn	
BKT	FAIR · Attn	
BKT Cylinder	FAIR · Attn	

UNDERCARRIAGE : See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3
COMMENT					
BKT	(STD / SLOPE / NARROW / SKELETON / OTHER ()				
Lever	LONG ▪ (WRIST)				
Multi	MULTI ▪ 2 ▪ (NO)				
ARM-CRANE	YES ▪ (NO)				
BLADE	YES ▪ (NO)				
OFFSET	YES ▪ (NO)				
OFFSET Cylinder	FAIR ▪ Attn				
Piping	YES ▪ (NO)	Breaker only ▪ Multi			
COMMENT					
底板欠 SOME UNDER COVERS: MISSING					
L03表示あり(E/G系統異常) "L03" ERROR DISPLAY FOR ENGINE					
ウォーターセパレータ警告あり					
WARNING LAMP FOR WATER SEPARATOR: ON					
A/Cベルト欠 A/C: NO BELT					
*1 破れあり、ヘッドレスト欠 CUTS, HEADREST: MISSING					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。