

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/4/8	MAKE	TOYOTA	MODEL	2SDK6		
SERIAL	2SDK6-10193			STAMP	NOT FOUND		
HR METER	2376	HR	Odometer	—	km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	10-16.5		

ENGINE : MODEL S/N Oil leakage <input checked="" type="radio"/> FAIR · Attn Blow-By <input checked="" type="radio"/> FAIR · Attn A LITTLE · MIDDLE · SEVERE Sound <input checked="" type="radio"/> FAIR · Attn Oil <input checked="" type="radio"/> FAIR · Attn Exhaust Color <input checked="" type="radio"/> FAIR · Attn US EPA YES · <input checked="" type="radio"/> NO OPERATION PUMP Sound <input checked="" type="radio"/> FAIR · Attn Oil leakage <input checked="" type="radio"/> FAIR · Attn Power <input checked="" type="radio"/> FAIR · Attn COOLING SYSTEM Radiator <input checked="" type="radio"/> FAIR · Attn Oil Cooler <input checked="" type="radio"/> FAIR · Attn TRANSMISSION & TRAVEL T/M TYPE <input checked="" type="radio"/> PS · DD Transmission <input checked="" type="radio"/> FAIR · Attn Travel <input checked="" type="radio"/> FAIR · Attn *1 FOOT BRAKE FAIR · Attn PARKING BRAKE FAIR · <input checked="" type="radio"/> Attn 効かない MALFUNCTION INTERIOR See Photos. 写真参照 INTERIOR COND. CLEAN · <input checked="" type="radio"/> FAIR · DIRTY Operator's Seat FAIR · <input checked="" type="radio"/> Attn 座面外れあり SEAT CUSHION: COME OFF Glasses FAIR · Attn AirCon A/C · H/C · H only · C only · <input checked="" type="radio"/> None FRONT & CYLINDERS Arm FAIR · <input checked="" type="radio"/> Attn 左右シリンダーサビあり CYLINDERS: RUSTY Bell crank FAIR · Attn Bucket FAIR · <input checked="" type="radio"/> Attn 左右シリンダーサビあり CYLINDERS: RUSTY Articulate FAIR · Attn	UNDERCARRIAGE : See Photos. 写真参照 RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 2 TIRE WEAR <input checked="" type="radio"/> FAIR · WORN · UNEVEN WEAR COMMENT STEERING TYPE WHEEL STEERING / COMMAND STEERING / <input checked="" type="radio"/> LEVER STEERING RIDE CONTROL YES · <input checked="" type="radio"/> NO ATTACHMENTS STD BKT <input checked="" type="radio"/> YES · OTHER BLADE YES · <input checked="" type="radio"/> NO Piping for Tilt YES · <input checked="" type="radio"/> NO COMMENT アクセルレバー押さえていないとローアイドル側へ戻る ACCELERATOR LEVER: MOVING TO LOW SIDE (NEED TO HOLD) バケット、アーム操作ペダル動き固い OPERATION PEDALS FOR BUCKET & ARM: STIFF *1 中立にしても少しずつ前に進む *1 SLOWLY TRAVELING FORWARD EVEN LEVER STEERING STAYS AT THE NEUTRAL POSITION RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 2
---	--

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。