

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/4/7	MAKE	KOBELCO	MODEL	SK120-3
SERIAL	NO PLATE			STAMP	LP-15133
HR METER	23635	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	700G

ENGINE : MODEL		S/N
Oil leakage	FAIR	Attn
Blow-By	FAIR	Attn
Sound	FAIR	Attn
Oil	FAIR	Attn
Exhaust Color	FAIR	Attn
US EPA	YES	NO
MAIN PUMP		
Sound	FAIR	Attn
Oil leakage	FAIR	Attn
Power	FAIR	Attn
COOLING SYSTEM		
Radiator	FAIR	Attn
Oil Cooler	FAIR	Attn
OPERATING SYSTEM		
Swing	FAIR	Attn
Travel	FAIR	Attn
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN	FAIR
Operator's Seat	FAIR	Attn
Glasses	FAIR	Attn
AirCon	A/C	H/C H only C only None
BOOM / ARM / BKT		
Boom	FAIR	Attn
Boom Cylinder	FAIR	Attn
Arm	FAIR	Attn
Arm Cylinder	FAIR	Attn
BKT	FAIR	Attn
BKT Cylinder	FAIR	Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
COMMENT	
左キャリアローラー変形あり LEFT CARRIER ROLLER: BENT	
BKT (STD / SLOPE / NARROW / SKELETON / OTHER ())	
Lever	LONG WRIST
Multi	MULTI 2 NO
ARM-CRANE	YES NO
BLADE	YES NO
OFFSET	YES NO
OFFSET Cylinder	FAIR Attn
Piping	YES NO Breaker only Multi *1
COMMENT	
A/Cあるが冷風出ない A/C: MALFUNCTION	
マフラー上部、配管途中壊れあり	
MUFFLER END PIPE: & SOME PART OF MUFFLER PIPES: BROKEN	
「E/Gオイルをかえてください」の表示が出る(オイルは入っている)	
WARNING DISPLAY FOR ENGINE OIL CHANGE (ENGINE OIL LEVEL: OK)	
*1 配管ペダルを踏むと右シューが動く、油圧ホース: バイパスあり	
*1 RIGHT TRACK MOVING WHEN STEPPING ON THE PIPING PEDAL,	
HOSES: W/BYPASS	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
2	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。