

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/4/2	MAKE	HITACHI	MODEL	ZW100-6
SERIAL	RYUNSCA0PH8811365			STAMP	H88-11365
HR METER	14770	HR	Odometer	22979	km
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE	YEAR	2019	YR	
TIRE SIZE	13.00-24				

ENGINE : MODEL		S/N
Oil leakage	FAIR	Attn
Blow-By	FAIR	Attn A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn
Oil	FAIR	Attn
Exhaust Color	FAIR	Attn
US EPA	YES	NO
OPERATION PUMP		
Sound	FAIR	Attn
Oil leakage	FAIR	Attn
Power	FAIR	Attn
COOLING SYSTEM		
Radiator	FAIR	Attn
Oil Cooler	FAIR	Attn
TRANSMISSION & TRAVEL		
T/M TYPE	PS	DD
Transmission	FAIR	Attn *1
Travel	FAIR	Attn *2
FOOT BRAKE	FAIR	Attn
PARKING BRAKE	FAIR	Attn
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN	FAIR · DIRTY
Operator's Seat	FAIR	Attn 破れあり HUGE CUTS
Glasses	FAIR	Attn F割れあり WINDSHIELD: CRACKED
AirCon	A/C	H/C · H only · C only · None
FRONT & CYLINDERS		
Arm	FAIR	Attn *3
Bell crank	FAIR	Attn
Bucket	FAIR	Attn
Articulate	FAIR	Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR	FAIR · WORN · UNEVEN WEAR
COMMENT	
エアボスタイヤ AIR BOSS TIRES	
STEERING TYPE WHEEL STEERING / COMMAND STEERING / LEVER STEERING	
RIDE CONTROL	YES · NO
ATTACHMENTS	
STD BKT	YES · OTHER *4
BLADE	YES · NO Piping for Tilt YES · NO
COMMENT	
CABドアラッチ破損あり DOOR LATCH: BROKEN	
エラー、！マーク表示あり ERROR & WARNING DISPLAY	
アームで車体上がらない UNABLE TO PUSH UP THE BODY BY ARM	
*1 アクセル欠のため変速確認不可(増速不可)	
*1 NOT CHECKED (ACCELERATOR PEDAL: MISSING)	
*2 5km/hぐらいまでしかスピード出ない(クリープ現象で走るだけ)、 アクセルペダル欠	
*2 MAXIMUM SPEED: ABOUT 5km/h (JUST MOVING WITH THE CREEP EFFECT).	
ACCELERATOR PEDAL: MISSING	
*3 目線の高さくらいからアーム動作重い (レバーを倒す戻すを繰り返すと少しずつ上昇する)	
ARM: HARD TO GO UP FROM OPERATOR'S HEIGHT (ABLE TO GO UP LITTLE BY LITTLE BY REPEATEDLY TILTING & PUTTING BACK THE LEVER)	
*4 グラップルバケット(左ツメ動作遅い)	
*4 GRAPPLE BUCKET (LEFT FORK: SLOW MOVING)	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。