

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/3/7	MAKE	TADANO	MODEL	TR-350M-3
SERIAL No.	PLATE : 506022		STAMP : TR352-0021		
HR METER	4677	HR	Odometer	9188	km
TIRE SIZE	445/95R25		YEAR	YR	

ENGINE : MODEL		S/N
Oil leakage	FAIR • Attn	
Blow-By	FAIR • Attn	A LITTLE • MIDDLE • SEVERE
Sound	FAIR • Attn	
Oil	FAIR • Attn	
Exhaust Color	FAIR • Attn	

OPERATION PUMP		
Sound	FAIR	Attn
Oil leakage	FAIR	Attn
Power	FAIR	Attn

COOLING SYSTEM		
Radiator	FAIR	Attrn
Oil Cooler	FAIR	Attrn

OPERATING SYSTEM		
Computer	OK・NG	CPUエラー表示あり CPU ERROR DISPLAY
Swing	FAIR・Attn	
Travel	FAIR・Attn	

TRANSMISSION			
Transmission	FAIR	Attn	
No. OF GEARS	4	GEARS	
No. of DRIVE WHEELS	4	WD	

INTERIOR		See Photos. 写真参照
Operator's Seat	FAIR ・ Attn	破れあり CUTS
Inside Cover	FAIR ・ Attn	
Glasses	FAIR ・ Attn	
AirCon	A/C ・ H/C ・ H only ・ C only ・ None	

COMMENT	

BOOM		
No. of Section	5	SECTIONS
CRACK/ENFORCEMENT	☐ FAIR ▪ Attn	
DERRICKING CYL.	☐ FAIR ▪ Attn	
EXTENSION CYL.	☐ FAIR ▪ Attn	
JIB	☐ YES ▪ NO	
JIB TYPE	STD ▪ ☐ PWR	
MAIN & SUB WIRE	☐ YES ▪ NO	
HOOK	20t, BALL	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

COMMENT

OUTRIGGERS		
OUTRIGGERS	(X) ▪ H	
OUTRIGGERS COND.	(FAIR) ▪ Attn	

COMMENT

ブーム伸縮切替えS/W不良、非常伸縮にてブーム伸縮可

BOOM TELESCOPE SWITCH: MALFUNCTION,

ABLE TO TELESCOPE IN THE EMERGENCY MODE

35tフック欠 35t HOOK: MISSING

[illegible]

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。