

INSPECTION SHEET 検品書  
CRAWLER DRILL クローラドリル

INSPECTION DATE	2025/3/27	MAKE	BAUER	MODEL	MG20
SERIAL	1108	STAMP	NOT FOUND		
HR METER	5756	HR	YEAR		YR
CAB/CNP	CAB / CNP / NONE	SHOE	500G PADS		
DRIFTER MODEL	-				

ENGINE : MODEL		S/N
Oil leakage	FAIR · <input checked="" type="radio"/> Attn	*1
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · <input checked="" type="radio"/> NO	
MAIN PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	
COOLING SYSTEM		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	
OPERATING SYSTEM		
Swing	FAIR · Attn	
Travel	FAIR · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · <input checked="" type="radio"/> DIRTY	
Operator's Seat	FAIR · Attn	
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · None	
DRIFTER HYDR.		
Lift	FAIR · Attn	
Swing	FAIR · Attn	
Tilt	FAIR · Attn	
Slide	FAIR · Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
Guide(Slide Length) mm	
Rod Changer	YES · NO
Drifter	YES · NO
Compressor	YES · NO
Blow	YES · NO
COMMENT	
左Rアウトリガー配管油漏れあり	
HYDRAULIC HOSE FOR REAR LEFT OUTRIGGER: OIL LEAKING	
E/G回転数調整ツマミ空回りする	
ENGINE SPEED ADJUSTMENT KNOB: SPINNING WITHOUT CATCHING	
ウインチペダル欠 WINCH PEDAL: MISSING	
A/C風出ない A/C: NOT BLOWING AIR	
動作未確認 OPERATION OF IMPLEMENTS: NOT CHECKED	
*1 オイルパン周り油漏れ小 AROUND OIL PAN: OIL LEAKING	
@SAKURA YARD	
リーダー、1軸オーガ LEADER, AUGER (1 AXIS)	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
2	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。