

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/3/7	MAKE	KOBELCO	MODEL	SK70SR-2
SERIAL	YT06-20024		STAMP	YT06-20024	
HR METER	3348	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	450G PADS	

ENGINE : MODEL 4LE2 **S/N** 283723

Oil leakage	<input checked="" type="radio"/> FAIR	· Attn	
Blow-By	<input checked="" type="radio"/> FAIR	<input checked="" type="radio"/> Attn	A LITTLE <input checked="" type="radio"/> MIDDLE <input type="radio"/> SEVERE
Sound	<input checked="" type="radio"/> FAIR	· Attn	
Oil	<input checked="" type="radio"/> FAIR	· Attn	
Exhaust Color	<input checked="" type="radio"/> FAIR	· Attn	
US EPA	<input checked="" type="radio"/> YES	· NO	

MAIN PUMP

Sound	<input checked="" type="radio"/> FAIR	· Attn	
Oil leakage	<input checked="" type="radio"/> FAIR	· Attn	
Power	<input checked="" type="radio"/> FAIR	· Attn	

COOLING SYSTEM

Radiator	<input checked="" type="radio"/> FAIR	· Attn	
Oil Cooler	<input checked="" type="radio"/> FAIR	· Attn	

OPERATING SYSTEM

Swing	<input checked="" type="radio"/> FAIR	· Attn	
Travel	<input checked="" type="radio"/> FAIR	· Attn	

INTERIOR See Photos. 写真参照

Operator's Seat	<input checked="" type="radio"/> FAIR	· Attn	破れあり TORN
Inside Cover	<input checked="" type="radio"/> FAIR	· Attn	
Glasses	<input checked="" type="radio"/> FAIR	· Attn	
AirCon	<input checked="" type="radio"/> A/C	· H/C	· H only · C only · None

BOOM / ARM / BKT

Boom	<input checked="" type="radio"/> FAIR	· Attn	
Boom Cylinder	<input checked="" type="radio"/> FAIR	· Attn	
Arm	<input checked="" type="radio"/> FAIR	· Attn	
Arm Cylinder	<input checked="" type="radio"/> FAIR	· Attn	
BKT	<input checked="" type="radio"/> FAIR	· Attn	
BKT Cylinder	<input checked="" type="radio"/> FAIR	· Attn	メッキ剥がれあり COATING: PEELED

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 4

COMMENT

.....

.....

.....

.....

BKT STD / SLOPE / NARROW / SKELETON / OTHER ()

Lever LONG · WRIST

Multi MULTI · 2 · NO

ARM-CRANE YES · NO

BLADE YES · NO

OFFSET YES · NO

OFFSET Cylinder FAIR · Attn

Piping YES · NO Breaker only Multi

COMMENT

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。