

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/4/7	MAKE	KOMATSU	MODEL	PC50UU-2E
SERIAL	14417			STAMP	14417
HR METER	8170	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	400ROAD LINER

ENGINE : MODEL		S/N
Oil leakage	FAIR ☒ Attn	油汚れあり OIL STAINS
Blow-By	FAIR ☒ Attn	A LITTLE ☐ MIDDLE ☐ SEVERE ☐
Sound	FAIR ☒ Attn	
Oil	FAIR ☒ Attn	
Exhaust Color	FAIR ☒ Attn	
US EPA	YES ☐ NO ☒	
MAIN PUMP		
Sound	FAIR ☒ Attn	
Oil leakage	FAIR ☒ Attn	
Power	FAIR ☒ Attn	
COOLING SYSTEM		
Radiator	FAIR ☒ Attn	
Oil Cooler	FAIR ☒ Attn	
OPERATING SYSTEM		
Swing	FAIR ☒ Attn	
Travel	FAIR ☒ Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN ☐ FAIR ☒ DIRTY ☐	
Operator's Seat	FAIR ☒ Attn	破れあり TORN
Glasses	FAIR ☒ Attn	
AirCon	A/C ☐ H/C ☐ H only ☐ C only ☐ None ☒	
BOOM / ARM / BKT		
Boom	FAIR ☒ Attn	ガタあり LOOSE
Boom Cylinder	FAIR ☒ Attn	
Arm	FAIR ☒ Attn	
Arm Cylinder	FAIR ☒ Attn	
BKT	FAIR ☒ Attn	ガタ、穴あり LOOSE, CRACKED
BKT Cylinder	FAIR ☒ Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
COMMENT	
BKT	STD ☒ SLOPE ☐ NARROW ☐ SKELETON ☐ OTHER () ☐
Lever	LONG ☐ WRIST ☒
Multi	MULTI ☐ 2 ☐ NO ☒
ARM-CRANE	YES ☐ NO ☒
BLADE	YES ☒ NO ☐
OFFSET	YES ☒ NO ☐
OFFSET Cylinder	FAIR ☒ Attn
Piping	YES ☐ NO ☒ Breaker only ☐ Multi ☐
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。