

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

|                 |                                                                         |      |         |                   |            |
|-----------------|-------------------------------------------------------------------------|------|---------|-------------------|------------|
| INSPECTION DATE | 2025/4/7                                                                | MAKE | KOMATSU | MODEL             | PC138US-10 |
| SERIAL          | 44250                                                                   |      | STAMP   | KMTPC245PFA044250 |            |
| HR METER        | 9969                                                                    | HR   | YEAR    | YR                |            |
| CAB/CNP         | <input checked="" type="radio"/> ROPS CAB / CAB / ROPS CNP / CNP / NONE |      | SHOE    | 500G              |            |

|                                  |                                                                     |                            |
|----------------------------------|---------------------------------------------------------------------|----------------------------|
| <b>ENGINE : MODEL</b>            |                                                                     | <b>S/N</b>                 |
| Oil leakage                      | <input checked="" type="radio"/> FAIR • Attn                        |                            |
| Blow-By                          | <input checked="" type="radio"/> FAIR • Attn                        | A LITTLE • MIDDLE • SEVERE |
| Sound                            | <input checked="" type="radio"/> FAIR • Attn                        |                            |
| Oil                              | <input checked="" type="radio"/> FAIR • Attn                        |                            |
| Exhaust Color                    | <input checked="" type="radio"/> FAIR • Attn                        |                            |
| US EPA                           | YES • <input checked="" type="radio"/> NO                           |                            |
| <b>MAIN PUMP</b>                 |                                                                     |                            |
| Sound                            | <input checked="" type="radio"/> FAIR • Attn                        |                            |
| Oil leakage                      | <input checked="" type="radio"/> FAIR • Attn                        |                            |
| Power                            | <input checked="" type="radio"/> FAIR • Attn                        |                            |
| <b>COOLING SYSTEM</b>            |                                                                     |                            |
| Radiator                         | <input checked="" type="radio"/> FAIR • Attn                        |                            |
| Oil Cooler                       | <input checked="" type="radio"/> FAIR • Attn                        |                            |
| <b>OPERATING SYSTEM</b>          |                                                                     |                            |
| Swing                            | <input checked="" type="radio"/> FAIR • Attn                        |                            |
| Travel                           | <input checked="" type="radio"/> FAIR • Attn                        |                            |
| <b>INTERIOR See Photos. 写真参照</b> |                                                                     |                            |
| INTERIOR COND.                   | CLEAN • FAIR • <input checked="" type="radio"/> DIRTY               |                            |
| Operator's Seat                  | <input checked="" type="radio"/> FAIR • Attn                        |                            |
| Glasses                          | <input checked="" type="radio"/> FAIR • Attn                        |                            |
| AirCon                           | <input checked="" type="radio"/> A/C • H/C • H only • C only • None |                            |
| <b>BOOM / ARM / BKT</b>          |                                                                     |                            |
| Boom                             | <input checked="" type="radio"/> FAIR • Attn                        |                            |
| Boom Cylinder                    | <input checked="" type="radio"/> FAIR • Attn                        |                            |
| Arm                              | <input checked="" type="radio"/> FAIR • Attn                        |                            |
| Arm Cylinder                     | <input checked="" type="radio"/> FAIR • Attn                        |                            |
| BKT                              | <input checked="" type="radio"/> FAIR • Attn                        | ガタあり LOOSE                 |
| BKT Cylinder                     | <input checked="" type="radio"/> FAIR • Attn                        |                            |

|                                                                      |                                                                              |
|----------------------------------------------------------------------|------------------------------------------------------------------------------|
| <b>UNDERCARRIAGE : See Photos. 写真参照</b>                              |                                                                              |
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)         | 2                                                                            |
| <b>COMMENT</b>                                                       |                                                                              |
|                                                                      |                                                                              |
|                                                                      |                                                                              |
|                                                                      |                                                                              |
|                                                                      |                                                                              |
|                                                                      |                                                                              |
|                                                                      |                                                                              |
| BKT                                                                  | <input checked="" type="radio"/> STD / SLOPE / NARROW / SKELETON / OTHER ( ) |
| Lever                                                                | LONG • <input checked="" type="radio"/> WRIST                                |
| Multi                                                                | MULTI • 2 • <input checked="" type="radio"/> NO                              |
| ARM-CRANE                                                            | <input checked="" type="radio"/> YES • NO                                    |
| BLADE                                                                | YES • <input checked="" type="radio"/> NO                                    |
| OFFSET                                                               | YES • <input checked="" type="radio"/> NO                                    |
| OFFSET Cylinder                                                      | FAIR • Attn                                                                  |
| Piping                                                               | YES • <input checked="" type="radio"/> NO Breaker only • Multi               |
| <b>COMMENT</b>                                                       |                                                                              |
| 全体的にコンクリート付着あり OVERALL CONCRETE STAINS                               |                                                                              |
|                                                                      |                                                                              |
|                                                                      |                                                                              |
|                                                                      |                                                                              |
|                                                                      |                                                                              |
|                                                                      |                                                                              |
|                                                                      |                                                                              |
|                                                                      |                                                                              |
|                                                                      |                                                                              |
|                                                                      |                                                                              |
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 2                                                                            |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。