

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2025/4/1	MAKE	KOMATSU	MODEL	D65PX-15
SERIAL	67267		STAMP	KMT0D029P01067267	
HR METER	8487	HR	SHOE	950LGP	YEAR YR
BLADE	STRAIGHT (ST/TILT) PAT / ANGLE / OTHER		CAB/CNP	(ROPS CAB) / CAB / ROPS CNP / CNP / NONE	

ENGINE : MODEL	S/N
Oil leakage (FAIR) · Attn	
Blow-By (FAIR) · Attn	A LITTLE · MIDDLE · SEVERE
Sound (FAIR) · Attn	
Oil (FAIR) · Attn	
Exhaust Color (FAIR) · Attn	
US EPA (YES) · NO	
OPERATION PUMP	
Sound (FAIR) · Attn	
Oil leakage (FAIR) · Attn	
Power (FAIR) · Attn	
COOLING SYSTEM	
Radiator (FAIR) · Attn	
Oil Cooler (FAIR) · Attn	
TRANSMISSION & TRAVEL	
T/M TYPE (PS) · DD	DIFF. STEERING (YES) · NO
Transmission (FAIR) · Attn	
Travel (FAIR) · Attn	
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN · (FAIR) · DIRTY
Operator's Seat (FAIR) · Attn	
Glasses (FAIR) · Attn	
AirCon (A/C) · H/C · H only · C only · None	
BLADE & CYLINDERS	
BLADE (FAIR) · Attn	
CYLD.(R) (FAIR) · Attn	
CYLD.(L) (FAIR) · Attn	
TILT CYLD (FAIR) · Attn	
ANGLE CYLD (FAIR) · Attn	

UNDERCARRIAGE See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			4
COMMENT			
Ripper	MULTI · S/S	Shanks	PCS
Ripper CYLD.	(FAIR) · Attn		
EQUALIZER BAR	(FAIR) · Attn		
COMMENT			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。