

INSPECTION SHEET 検品書
CRAWLER CRANE クローラクレーン

INSPECTION DATE	2025/4/8	MAKE	SUMITOMO	MODEL	SC550-2
SERIAL No.	PLATE :	SC055-1310	STAMP	SC055-1310	
HR METER	1814	HR	SHOE	760FLAT	YEAR YR

ENGINE : MODEL		S/N	TA42164
Oil leakage	<input checked="" type="radio"/> FAIR	Attn	
Blow-By	<input checked="" type="radio"/> FAIR	A LITTLE · MIDDLE · <input checked="" type="radio"/> SEVERE	
Sound	<input checked="" type="radio"/> FAIR	Attn	
Oil	<input checked="" type="radio"/> FAIR	Attn	
Exhaust Color	<input checked="" type="radio"/> FAIR	Attn	
OPERATION PUMP			
Sound	<input checked="" type="radio"/> FAIR	Attn	
Oil leakage	<input checked="" type="radio"/> FAIR	Attn	
Power	<input checked="" type="radio"/> FAIR	Attn	
COOLING SYSTEM			
Radiator	<input checked="" type="radio"/> FAIR	Attn	
Oil Cooler	<input checked="" type="radio"/> FAIR	Attn	
OPERATING SYSTEM			
Computer	<input checked="" type="radio"/> OK	NG	
Swing	<input checked="" type="radio"/> FAIR	Attn	
Travel	<input checked="" type="radio"/> FAIR	Attn	
BOOM			
MAIN BOOM	TOP, BOTTOM, 6m × 4		
BOOM TOTAL	36m		
TOP SHEAVE	<input checked="" type="radio"/> YES	NO	
JIB			
TOWER			

INTERIOR		See Photos. 写真参照	
INTERIOR COND.	CLEAN · FAIR · <input checked="" type="radio"/> DIRTY		
Operator's Seat	<input checked="" type="radio"/> FAIR	破れあり TORN	
Glasses	<input checked="" type="radio"/> FAIR	Attn	
AirCon	<input checked="" type="radio"/> A/C	H/C · H only · C only · None	
UNDERCARRIAGE : See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3
COMMENT			
WEIGHT		2	
HOOK		55t, BALL	
LIFTER		YES · <input checked="" type="radio"/> NO	
COMMENT			
@NARITA YARD			
BOOM: TOP, BOTTOM, 6m × 1			
@YOTSUKAIDO YARD			
BOOM: 6m × 3			
BALL HOOK			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。