

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/6/6	MAKE	KOMATSU	MODEL	PC60-6
SERIAL	36312		STAMP	PC60-36312	
HR METER	7096	HR	YEAR	1991	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	700LGP	

ENGINE : MODEL		4D95L-1	S/N
Oil leakage	FAIR	Attn	
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
US EPA	YES	NO	
MAIN PUMP			
Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	
COOLING SYSTEM			
Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	
OPERATING SYSTEM			
Swing	FAIR	Attn	ガタあり SWING: LOOSE
Travel	FAIR	Attn	
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN	FAIR	DIRTY
Operator's Seat	FAIR	Attn	破れあり TORN
Glasses	FAIR	Attn	
AirCon	A/C	H/C	H only · C only · None
BOOM / ARM / BKT			
Boom	FAIR	Attn	
Boom Cylinder	FAIR	Attn	*1
Arm	FAIR	Attn	
Arm Cylinder	FAIR	Attn	
BKT	FAIR	Attn	
BKT Cylinder	FAIR	Attn	

UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
COMMENT		
BKT	STD / SLOPE / NARROW / SKELETON / OTHER()	
Lever	LONG • WRIST	
Multi	MULTI • 2 • NO	
ARM-CRANE	YES • NO	
BLADE	YES • NO	
OFFSET	YES • NO	
OFFSET Cylinder	FAIR • Attn	
Piping	YES • NO	Breaker only • Multi
COMMENT		
ブーム背面ホースひび割れ、破れあり		
HOSES AROUND LOWER PART OF BOOM: CRACKED, CUTS		
左操作レバー中立が曖昧(アーム動作していると旋回に入る)		
LEFT OPERATION LEVER: INDEFINITE NEUTRAL POSITION		
(SUDDENLY SWINGING WHEN OPERATING THE ARM)		
CABドア中から開かない DOOR: UNABLE TO OPEN FROM INSIDE		
*1 にじみ、シリンダーホースひび割れあり OIL OOZING, HOSE: CRACKED		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。