

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/6/6	MAKE	YANMAR	MODEL	B27-2
SERIAL	42553B			STAMP	42553B
HR METER	3148	HR	YEAR	1993	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	320R

ENGINE : MODEL		S/N	16690
Oil leakage	FAIR	Attn	
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
US EPA	YES	NO	
MAIN PUMP			
Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	
COOLING SYSTEM			
Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	
OPERATING SYSTEM			
Swing	FAIR	Attn	ゴリゴリ感小、ガタあり RATTLING, SWING: LOOSE
Travel	FAIR	Attn	
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN	FAIR	DIRTY
Operator's Seat	FAIR	Attn	破れあり CUTS
Glasses	FAIR	Attn	*1
AirCon	A/C	H/C	H only · C only · None
BOOM / ARM / BKT			
Boom	FAIR	Attn	ガタあり LOOSE
Boom Cylinder	FAIR	Attn	油漏れあり OIL LEAKING
Arm	FAIR	Attn	ガタあり LOOSE
Arm Cylinder	FAIR	Attn	油漏れ小 OIL LEAKING
BKT	FAIR	Attn	
BKT Cylinder	FAIR	Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
BKT (STD / SLOPE / NARROW / SKELETON / OTHER ())	
Lever	LONG · WRIST
Multi	MULTI · 2 · NO
ARM-CRANE	YES · NO
BLADE	YES · NO
OFFSET	YES · NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · NO Breaker only · Multi
COMMENT	
プレート: 塗装で見にくい PLATE: HARD TO READ (PAINTED)	
水温計点灯あり WARNING LAMP FOR WATER TEMPERATURE GAUGE: ON	
バッテリーチェック点灯する時あり(10秒に1回?)	
BATTERY WARNING LAMP: ON ONCE PER ABOUT 10 SECONDS	
スイング部ガタあり SWING PART: LOOSE	
*1 Fひび割れ、天窓外れあり	
*1 UPPER WINDSHIELD: CRACKED,	
SKYLIGHT: COME OFF (FIXED WITH ADHESIVE TAPES)	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
2	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。