

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/4/8	MAKE	KOBELCO	MODEL	RK120-2
SERIAL No.	PLATE : FK1147		STAMP : TR120-5147		
HR METER	12381	HR	Odometer	139686	km
TIRE SIZE	275/80R22.5		YEAR	2008	YR

ENGINE : MODEL		S/N	
Oil leakage	FAIR	Attn	*1
Blow-By	FAIR	Attn	A LITTLE • MIDDLE • SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
OPERATION PUMP			
Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	
COOLING SYSTEM			
Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	
OPERATING SYSTEM			
Computer	OK	NG	
Swing	FAIR	Attn	
Travel	FAIR	Attn	
TRANSMISSION			
Transmission	FAIR	Attn	*2
No. OF GEARS	3	GEARS	
4WD	4WD	6WD	
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN • FAIR •	DIRTY	
Operator's Seat	FAIR	Attn	
Glasses	FAIR	Attn	
AirCon	A/C •	H/C • H only • C only • None	
COMMENT			

BOOM					
No. of Section	6		SECTIONS		
CRACK/ENFORCEMENT	FAIR	▪	Attn		
DERRICKING CYL.	FAIR	▪	Attn		
EXTENSION CYL.	FAIR	▪	Attn		
JIB	YES	▪	NO		
JIB TYPE	STD	▪	PWR		
MAIN & SUB WIRE	YES	▪	NO		
HOOK	12t, BALL				
UNDERCARRIAGE : See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					1
TIRE WEAR	FAIR ▪ WORN ▪ UNEVEN WEAR				
COMMENT					
OUTRIGGERS					
OUTRIGGERS	X	▪	H		
OUTRIGGERS COND.	FAIR	▪	Attn		
Oil leakage (JACK CYL.)	FRONT	L	▪	R	REAR L ▪ R
Oil leakage (SLIDE CYL.)	FRONT	L	▪	R	REAR L ▪ R
COMMENT					
ブーム先端ガイドリール変形あり GUIDE REEL OF BOOM TOP: BENT					
*1 E/Gとトルコンの継ぎ目からにじみあり					
*1 CONNECTING PART BETWEEN ENGINE & TORQUE CONVERTER: OIL LEAKING					
*2 ゲージ付近油漏れあり AROUND OIL GAUGE: OIL LEAKING					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。