

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/4/4	MAKE	HITACHI	MODEL	EX70LCK-5
SERIAL	1C2P054074		STAMP	1C2P054074	
HR METER	6167	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	450G PADS	

ENGINE : MODEL		S/N	
Oil leakage	FAIR · ☒ Attn	*1	
Blow-By	FAIR · ☐ Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR · ☐ Attn		
Oil	FAIR · ☐ Attn		
Exhaust Color	FAIR · ☐ Attn		
US EPA	YES · ☒ NO		
MAIN PUMP			
Sound	FAIR · ☐ Attn		
Oil leakage	FAIR · ☐ Attn		
Power	FAIR · ☐ Attn		
COOLING SYSTEM			
Radiator	FAIR · ☐ Attn	サブタンク割れあり SUB TANK: DAMAGED	
Oil Cooler	FAIR · ☐ Attn		
OPERATING SYSTEM			
Swing	FAIR · ☐ Attn	ガタあり SWING: LOOSE	
Travel	FAIR · ☐ Attn		
INTERIOR		See Photos. 写真参照	
INTERIOR COND.	CLEAN · FAIR · ☒ DIRTY		
Operator's Seat	FAIR · ☒ Attn	穴あり TINY HOLES	
Glasses	FAIR · ☐ Attn		
AirCon	☒ A/C · H/C · H only · C only · None		
BOOM / ARM / BKT			
Boom	FAIR · ☐ Attn		
Boom Cylinder	FAIR · ☐ Attn		
Arm	FAIR · ☐ Attn	スライドアーム SLIDE ARM	
Arm Cylinder	FAIR · ☐ Attn		
BKT	FAIR · ☐ Attn		
BKT Cylinder	FAIR · ☐ Attn		

UNDERCARRIAGE :		See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3	
COMMENT			
BKT	STD / SLOPE / NARROW / ☒ SKELETON / OTHER ()		
Lever	LONG · ☒ WRIST		
Multi	MULTI · 2 · ☒ NO		
ARM-CRANE	YES · ☒ NO		
BLADE	☒ YES · NO		
OFFSET	YES · ☒ NO		
OFFSET Cylinder	FAIR · ☐ Attn		
Piping	☒ YES · NO	Breaker only · ☒ Multi	
COMMENT			
機体外装リペイントあり REPAINTED			
ウォッシャータンク破損あり WASHER TANK: BROKEN			
*1 ヘッドカバー周りにじみあり AROUND HEAD COVER: OIL OOZING			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。