

INSPECTION SHEET 検品書
CRAWLER CRANE クローラクレーン

INSPECTION DATE	2025/4/5	MAKE	KOMATSU	MODEL	LC755-3
SERIAL No.	PLATE :	30149	STAMP	30149	
HR METER	5703 + 371 HR	SHOE	450G PADS	YEAR	YR

ENGINE : MODEL		4D102E-1	S/N	26273284
Oil leakage	FAIR	・	Attn	周りにじみあり AROUND ENGINE: OIL OOZING
Blow-By	FAIR	・	Attn	A LITTLE ・ MIDDLE ・ SEVERE
Sound	FAIR	・	Attn	
Oil	FAIR	・	Attn	
Exhaust Color	FAIR	・	Attn	

OPERATION PUMP

Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	*1
Power	FAIR · Attn	

COOLING SYSTEM

Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	

OPERATING SYSTEM

Computer	OK · NG	
Swing	FAIR · Attn	
Travel	FAIR · Attn	

BOOM

MAIN BOOM	
BOOM TOTAL	

TOP SHEAVE	YES · NO

JIB	
-----	--

TOWER	
-------	--

--	--

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN	FAIR	DIRTY
----------------	-------	------	-------

Operator's Seat	FAIR	Attn	*2
-----------------	------	------	----

Glasses	FAIR	Attn	
---------	------	------	--

AirCon	A/C	H/C	H only	C only	None
--------	-----	------------	--------	--------	------

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
---	----------

COMMENT

WEIGHT	—
--------	---

HOOK	4.9t
------	------

LIFTER	YES · NO	
--------	----------	--

COMMENT

CAB

ドア上部ローラー外れあり UPPER GUIDE ROLLER OF DOOR: COME OFF

ラジオ音出ない RADIO: NOT SPEAKING

5段ブーム 5-SECTION BOOM

*1 下側油漏れ、付近にじみあり

*1 BOTTOM: OIL LEAKING, AROUND PUMP: OIL OOZING

*2 破れ、補修テープあり CUTS, COVERED WITH SOME ADHESIVE TAPE

.....

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
---	----------

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。