

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/4/4	MAKE	TADANO	MODEL	GR-160N-2
SERIAL No.	PLATE : 526162		STAMP : T006-0050		
HR METER	25792	HR	Odometer	152104	km
TIRE SIZE	325/95R24		YEAR	YR	

ENGINE : MODEL		S/N
Oil leakage	FAIR Attn	E/Gヘッドにじみあり CYLINDER HEAD: OIL OOZING
Blow-By	FAIR Attn	A LITTLE ・ MIDDLE ・ SEVERE
Sound	FAIR Attn	
Oil	FAIR Attn	
Exhaust Color	FAIR Attn	

OPERATION PUMP

Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	

COOLING SYSTEM

Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	

OPERATING SYSTEM

Computer	OK	NG
Swing	FAIR	Attn
Travel	FAIR	Attn

TRANSMISSION

Transmission	FAIR	Attn	
No. OF GEARS	4	GEARS	
4WD	4WD	6WD	

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN • FAIR • DIRTY	
Operator's Seat	FAIR • Attn	破れあり HUGE CUTS
Glasses	FAIR • Attn	
AirCon	A/C • H/C • H only • C only • None	

COMMENT

BOOM

No. of Section	6	SECTIONS	
CRACK/ENFORCEMENT	FAIR	▪ Attn	
DERRICKING CYL.	FAIR	▪ Attn	
EXTENSION CYL.	FAIR	▪ Attn	
JIB	YES	▪ NO	
JIB TYPE	STD	▪ PWR	
MAIN & SUB WIRE	YES	▪ NO	
HOOK	16t, BALL		

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		4
TIRE WEAR	FAIR • WORN • UNEVEN WEAR	

COMMENT

OUTRIGGERS

OUTRIGGERS	X	•	H		
OUTRIGGERS COND.	FAIR	•	Attn		
Oil leakage (JACK CYL.)	FRONT	L	•	R	REAR L • R
Oil leakage (SLIDE CYL.)	FRONT	L	•	R	REAR L • R

COMMENT

[illegible]

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
---	----------

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。