

**INSPECTION SHEET 検品書**  
**ROUGH TERRAIN CRANE ラフタークレーン**

INSPECTION DATE	2025/4/8	MAKE	KATO	MODEL	KRM-13H-II
SERIAL No.	PLATE : 5810313	STAMP :		KRC008-0313	
HR METER	16362	HR	Odometer	98574	km
TIRE SIZE	275/80R22.5	YEAR	YR		

<b>ENGINE : MODEL</b>		<b>S/N</b>
Oil leakage	FAIR <input checked="" type="radio"/> Attn *1	
Blow-By	FAIR <input checked="" type="radio"/> Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR <input checked="" type="radio"/> Attn	
Oil	FAIR <input checked="" type="radio"/> Attn	
Exhaust Color	FAIR <input checked="" type="radio"/> Attn	
<b>OPERATION PUMP</b>		
Sound	FAIR <input checked="" type="radio"/> Attn	
Oil leakage	FAIR <input checked="" type="radio"/> Attn	
Power	FAIR <input checked="" type="radio"/> Attn	
<b>COOLING SYSTEM</b>		
Radiator	FAIR <input checked="" type="radio"/> Attn	
Oil Cooler	FAIR <input checked="" type="radio"/> Attn	
<b>OPERATING SYSTEM</b>		
Computer	OK <input checked="" type="radio"/> NG	
Swing	FAIR <input checked="" type="radio"/> Attn	
Travel	FAIR <input checked="" type="radio"/> Attn	
<b>TRANSMISSION</b>		
Transmission	FAIR <input checked="" type="radio"/> Attn	
No. OF GEARS	4 GEARS	
4WD	4WD <input checked="" type="radio"/> 6WD	
<b>INTERIOR See Photos. 写真参照</b>		
INTERIOR COND.	CLEAN <input checked="" type="radio"/> FAIR · DIRTY	
Operator's Seat	FAIR <input checked="" type="radio"/> Attn	
Glasses	FAIR <input checked="" type="radio"/> Attn	
AirCon	A/C <input checked="" type="radio"/> H/C · H only · C only · None	
<b>COMMENT</b>		

<b>BOOM</b>			
No. of Section	6	SECTIONS	
CRACK/ENFORCEMENT	FAIR <input checked="" type="radio"/> Attn		
DERRICKING CYL.	FAIR <input checked="" type="radio"/> Attn		
EXTENSION CYL.	FAIR <input checked="" type="radio"/> Attn		
JIB	YES <input checked="" type="radio"/> NO		
JIB TYPE	STD · PWR <input checked="" type="radio"/>		
MAIN & SUB WIRE	YES <input checked="" type="radio"/> NO		
HOOK	13t, BALL		
<b>UNDERCARRIAGE : See Photos. 写真参照</b>			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1		
TIRE WEAR	FAIR <input checked="" type="radio"/> WORN · UNEVEN WEAR		
<b>COMMENT</b>			
<b>OUTRIGGERS</b>			
OUTRIGGERS	X · H <input checked="" type="radio"/>		
OUTRIGGERS COND.	FAIR <input checked="" type="radio"/> Attn		
Oil leakage (JACK CYL.)	FRONT	L · R	REAR L · R
Oil leakage (SLIDE CYL.)	FRONT	L · R	REAR L · R
<b>COMMENT</b>			
*1 E/G下部にじみあり BOTTOM OF ENGINE: OIL Oozing			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3		

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。