

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/4/3	MAKE	KOBELCO	MODEL	KRM-13H- II
SERIAL No.	PLATE :	5810119	STAMP :	KRC008-0119	
HR METER	23451	HR	Odometer	144828	km
TIRE SIZE	275/80R22.5		YEAR		YR

ENGINE : MODEL		S/N
Oil leakage	(FAIR) • Attn	
Blow-By	(FAIR) • Attn	A LITTLE • MIDDLE • SEVERE
Sound	(FAIR) • Attn	
Oil	(FAIR) • Attn	
Exhaust Color	(FAIR) • Attn	
OPERATION PUMP		
Sound	(FAIR) • Attn	
Oil leakage	(FAIR) • Attn	
Power	(FAIR) • Attn	
COOLING SYSTEM		
Radiator	(FAIR) • Attn	
Oil Cooler	(FAIR) • Attn	
OPERATING SYSTEM		
Computer	(OK) • NG	
Swing	(FAIR) • Attn	
Travel	(FAIR) • Attn	
TRANSMISSION		
Transmission	(FAIR) • Attn	
No. OF GEARS	3	GEARS
4WD	(4WD) • 6WD	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN • (FAIR) • DIRTY	
Operator's Seat	(FAIR) • Attn	
Glasses	(FAIR) • Attn	
AirCon	(A/C) • H/C • H only • C only • None	
COMMENT		

[illegible]

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。