

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/4/2	MAKE	KATO	MODEL	KRM-13H-II
SERIAL No.	PLATE : 5810149	STAMP :		KRC008-0149	
HR METER	22162	HR	Odometer	166175	km
TIRE SIZE	275/80R22.5	YEAR	YR		

ENGINE : MODEL		S/N
Oil leakage	<input type="radio"/> FAIR <input checked="" type="radio"/> Attn	ヘッド油漏れあり CYLINDER HEAD: OIL LEAKING
Blow-By	<input type="radio"/> FAIR <input type="radio"/> Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input type="radio"/> FAIR <input type="radio"/> Attn	
Oil	<input type="radio"/> FAIR <input type="radio"/> Attn	
Exhaust Color	<input type="radio"/> FAIR <input type="radio"/> Attn	
OPERATION PUMP		
Sound	<input type="radio"/> FAIR <input type="radio"/> Attn	
Oil leakage	<input type="radio"/> FAIR <input type="radio"/> Attn	
Power	<input type="radio"/> FAIR <input type="radio"/> Attn	
COOLING SYSTEM		
Radiator	<input type="radio"/> FAIR <input type="radio"/> Attn	
Oil Cooler	<input type="radio"/> FAIR <input type="radio"/> Attn	
OPERATING SYSTEM		
Computer	<input type="radio"/> OK <input checked="" type="radio"/> NG *1	
Swing	<input type="radio"/> FAIR <input type="radio"/> Attn	
Travel	<input type="radio"/> FAIR <input type="radio"/> Attn	
TRANSMISSION		
Transmission	<input type="radio"/> FAIR <input type="radio"/> Attn	
No. OF GEARS	4 GEARS	
4WD	<input checked="" type="radio"/> 4WD <input type="radio"/> 6WD	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	<input type="radio"/> CLEAN <input checked="" type="radio"/> FAIR <input type="radio"/> DIRTY	
Operator's Seat	<input type="radio"/> FAIR <input checked="" type="radio"/> Attn	破れあり HUGE CUT
Glasses	<input type="radio"/> FAIR <input type="radio"/> Attn	
AirCon	<input checked="" type="radio"/> A/C <input type="radio"/> H/C <input type="radio"/> H only <input type="radio"/> C only <input type="radio"/> None	
COMMENT		

BOOM			
No. of Section	6	SECTIONS	
CRACK/ENFORCEMENT	<input type="radio"/> FAIR <input type="radio"/> Attn		
DERRICKING CYL.	<input type="radio"/> FAIR <input type="radio"/> Attn		
EXTENSION CYL.	<input type="radio"/> FAIR <input type="radio"/> Attn		
JIB	<input checked="" type="radio"/> YES <input type="radio"/> NO		
JIB TYPE	<input type="radio"/> STD <input checked="" type="radio"/> PWR		
MAIN & SUB WIRE	<input checked="" type="radio"/> YES <input type="radio"/> NO		
HOOK	13t, BALL		
UNDERCARRIAGE : See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			4
TIRE WEAR	<input checked="" type="radio"/> FAIR <input type="radio"/> WORN <input type="radio"/> UNEVEN WEAR		
COMMENT			
OUTRIGGERS			
OUTRIGGERS	<input checked="" type="radio"/> X <input type="radio"/> H		
OUTRIGGERS COND.	<input type="radio"/> FAIR <input type="radio"/> Attn		
Oil leakage (JACK CYL.)	FRONT	L · R	REAR L · R
Oil leakage (SLIDE CYL.)	FRONT	L · R	REAR L · R
COMMENT			
*1 コードリール断線不良、非常用にて作動			
*1 CORD REEL: DISCONNECTED,			
ABLE TO OPERATE IN THE EMERGENCY MODE			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。