

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/4/3	MAKE	TADANO	MODEL	TR-100M-1
SERIAL No.	PLATE : FC0182		STAMP : TR100-0182		
HR METER	11532	HR	Odometer	100806	km
TIRE SIZE	11R22.5		YEAR	YR	

ENGINE : MODEL		S/N
Oil leakage	FAIR · Attn	*1
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
OPERATION PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	
COOLING SYSTEM		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	
OPERATING SYSTEM		
Computer	OK · NG	
Swing	FAIR · Attn	
Travel	FAIR · Attn	
TRANSMISSION		
Transmission	FAIR · Attn	
No. OF GEARS	3 GEAR	
4WD	4WD · 6WD	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · DIRTY	
Operator's Seat	FAIR · Attn	破れあり CUTS
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · None	
COMMENT		

BOOM					
No. of Section	6		SECTIONS		
CRACK/ENFORCEMENT	FAIR	▪	Attn		
DERRICKING CYL.	FAIR	▪	Attn		
EXTENSION CYL.	FAIR	▪	Attn		
JIB	YES	▪	NO		
JIB TYPE	STD	▪	PWR		
MAIN & SUB WIRE	YES	▪	NO		
HOOK	10t, BALL				
UNDERCARRIAGE : See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3
TIRE WEAR	FAIR • WORN • UNEVEN WEAR				
COMMENT					
OUTRIGGERS					
OUTRIGGERS	X	▪	H	*2	
OUTRIGGERS COND.	FAIR	▪	Attn		
Oil leakage (JACK CYL.)	FRONT	L	▪ R	REAR	L ▪ R
Oil leakage (SLIDE CYL.)	FRONT	L	▪ R	REAR	L ▪ R
COMMENT					
*1 上部油漏れあり UPPER PART OF ENGINE: OIL LEAKING					
*2 右Fアウトリガーストロークセンサ不良					
*2 FRONT RIGHT OUTRIGGER EXTENSION SENSOR: MALFUNCTION					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。