

INSPECTION SHEET 検品書

OTHER その他

INSPECTION DATE	2025/4/4	CATEGORY	木材運搬車 LUMBER TRANSPORT VEHICLE			
MAKE	OIKAWA MOTORS		MODEL	MTK-FGC		
SERIAL	03002		STAMP	NOT FOUND		
HR METER	3288	HR	Odometer	—	km	YEAR YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	320R	TIRE	—

ENGINE	MODEL	4JB1	S/N	721218
Oil leakage	FAIR • Attn		Oil	FAIR • Attn
Blow-By	FAIR • Attn	A LITTLE • MIDDLE • SEVERE	Exhaust Color	FAIR • Attn
Sound	FAIR • Attn		EPA	YES • NO

CONDITION	FAIR • Attn
ブーム背中側ホースひび割れあり HOSES AROUND LOWER PART OF BOOM: CRACKED	
ブームシリンダー、アームシリンダー、アームスライドシリンダー油漏れあり BOOM CYLINDER, ARM CYLINDER, & ARM SLIDE CYLINDER: OIL LEAKING	

UNDERCARRIAGE : See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3	TIRE WEAR	FAIR • WORN • UNEVEN WEAR
COMMENT			
グラップル付 W/GRAPPLE			
左右中折れシリンダーメッキ剥がれあり ARTICULATE CYLINDERS: COATING PEELED			
Fウインチワイヤー切れ、乱巻きあり FRONT WINCH WIRE: A LITTLE DAMAGED, IRREGULAR WINDING			
ベッセル版メクレあり VESSEL FLOOR: PEELED			
下側シート: ガタ、破れあり LOWER SEAT: LOOSE, HUGE CUTS			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3		

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。