

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2025/4/9	MAKE	CAT	MODEL	D6K
SERIAL	CAT00D6KJDHA00916			STAMP	CAT00D6KJDHA00916
HR METER	6439	HR	SHOE	770LGP	YEAR YR
BLADE	STRAIGHT / ST/TILT / PAT / ANGLE / OTHER			CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE

ENGINE : MODEL C6.6		S/N C6E13279	
Oil leakage	☒ FAIR • Attn		
Blow-By	☒ FAIR • Attn	A LITTLE • MIDDLE • SEVERE	
Sound	☒ FAIR • Attn		
Oil	☒ FAIR • Attn		
Exhaust Color	☒ FAIR • Attn		
US EPA	YES • ☒ NO		
OPERATION PUMP			
Sound	☒ FAIR • Attn		
Oil leakage	☒ FAIR • Attn		
Power	☒ FAIR • Attn		
COOLING SYSTEM			
Radiator	☒ FAIR • Attn		
Oil Cooler	☒ FAIR • Attn		
TRANSMISSION & TRAVEL			
T/M TYPE	☒ PS • DD	DIFF. STEERING	☒ YES • NO
Transmission	☒ FAIR • Attn		
Travel	☒ FAIR • Attn		
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN • ☒ FAIR • DIRTY		
Operator's Seat	FAIR • ☒ Attn	破れ大 TORN	
Glasses	☒ FAIR • Attn		
AirCon	☒ A/C • H/C • H only • C only • None		
BLADE & CYLINDERS			
BLADE	☒ FAIR • Attn		
CYLD.(R)	☒ FAIR • Attn		
CYLD.(L)	☒ FAIR • Attn		
TILT CYLD	☒ FAIR • Attn		
ANGLE CYLD	FAIR • ☒ Attn	*1	

UNDERCARRIAGE See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3
COMMENT			
Ripper	MULTI • S/S	Shanks	PCS
Ripper CYLD.	FAIR • Attn		
EQUALIZER BAR	FAIR • Attn		
COMMENT			
*1 右シリンダー油漏れあり RIGHT CYLINDER: OIL LEAKING			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。