

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/4/6	MAKE	TADANO	MODEL	GR-120N-1
SERIAL No.	PLATE : FD0889		STAMP : TR120-0884		
HR METER	20895	HR	Odometer	192545	km
TIRE SIZE	275/80R22.5		YEAR	YR	

ENGINE : MODEL		S/N	
Oil leakage	FAIR · Attn	上部にじみあり UPPER PART: OIL OOOZING	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR · Attn		
Oil	FAIR · Attn		
Exhaust Color	FAIR · Attn		
OPERATION PUMP			
Sound	FAIR · Attn		
Oil leakage	FAIR · Attn		
Power	FAIR · Attn		
COOLING SYSTEM			
Radiator	FAIR · Attn		
Oil Cooler	FAIR · Attn		
OPERATING SYSTEM			
Computer	OK · NG		
Swing	FAIR · Attn		
Travel	FAIR · Attn		
TRANSMISSION			
Transmission	FAIR · Attn		
No. OF GEARS	2	GEARS	
4WD	4WD · 6WD		
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN · FAIR · DIRTY		
Operator's Seat	FAIR · Attn		
Glasses	FAIR · Attn		
AirCon	A/C · H/C · H only · C only · None		
COMMENT			

BOOM							
No. of Section	6		SECTIONS				
CRACK/ENFORCEMENT	FAIR	▪ Attn					
DERRICKING CYL.	FAIR	▪ Attn					
EXTENSION CYL.	FAIR	▪ Attn					
JIB	YES	▪ NO					
JIB TYPE	STD	▪ PWR					
MAIN & SUB WIRE	YES	▪ NO					
HOOK	4.9t, BALL						
UNDERCARRIAGE : See Photos. 写真参照							
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)							3
TIRE WEAR	FAIR ▪ WORN ▪ UNEVEN WEAR						
COMMENT							
OUTRIGGERS							
OUTRIGGERS	X	▪ H					
OUTRIGGERS COND.	FAIR	▪ Attn					
Oil leakage (JACK CYL.)	FRONT	L	▪ R	REAR	L ▪ R		
Oil leakage (SLIDE CYL.)	FRONT	L	▪ R	REAR	L ▪ R		
COMMENT							
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)							3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。