

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/4/9	MAKE	KOBELCO	MODEL	SK30UR-5
SERIAL	PR08-10418		STAMP	PR08-10418	
HR METER	2598	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	300G PADS	

ENGINE : MODEL		S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · NO	
MAIN PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	
COOLING SYSTEM		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	
OPERATING SYSTEM		
Swing	FAIR · Attn	ガタあり SWING: LOOSE
Travel	FAIR · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · DIRTY	
Operator's Seat	FAIR · Attn	
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · None	
BOOM / ARM / BKT		
Boom	FAIR · Attn	2ピースブーム 2-PIECE BOOM
Boom Cylinder	FAIR · Attn	
Arm	FAIR · Attn	
Arm Cylinder	FAIR · Attn	
BKT	FAIR · Attn	油漏れあり OIL LEAKING
BKT Cylinder	FAIR · Attn	

UNDERCARRIAGE :		See Photos. 写真参照
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
COMMENT		
クローラ伸縮OK VARIABLE WIDTH UNDERCARRIAGE		
BKT	STD / SLOPE / NARROW / SKELETON / OTHER)	
Lever	LONG ・ WRIST	
Multi	MULTI ・ 2 ・ NO	
ARM-CRANE	YES ・ NO	
BLADE	YES ・ NO	*1
OFFSET	YES ・ NO	
OFFSET Cylinder	FAIR ・ Attn	
Piping	YES ・ NO	Breaker only ・ Multi 5
COMMENT		
アタッチメント:回転式フォークグラブ ATTACHMENT: ROTATABLE FORK GRAB		
MAKE: MARUJUN IFR35-2-170425-004		
付属品:スケルトンバケット SKELETON BUCKET AS SPARE		
*1 本体上がらない UNABLE TO PUSH UP THE BODY BY BLADE		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。