

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

| | | | | | |
|-----------------|---|------|---------|---|----------|
| INSPECTION DATE | 2025/4/3 | MAKE | KOMATSU | MODEL | D65PX-16 |
| SERIAL | 80900 | | STAMP | KMT0D114L01080900 | |
| HR METER | 3106 | HR | SHOE | 940LGP | YEAR YR |
| BLADE | STRAIGHT / <u>ST/TILT</u> / PAT / ANGLE / OTHER | | CAB/CNP | <u>ROPS CAB</u> / CAB / ROPS CNP / CNP / NONE | |

| | | |
|----------------------------------|---|--|
| ENGINE : MODEL | | S/N |
| Oil leakage | <input checked="" type="radio"/> FAIR · Attn | |
| Blow-By | <input checked="" type="radio"/> FAIR · Attn | A LITTLE · MIDDLE · SEVERE |
| Sound | <input checked="" type="radio"/> FAIR · Attn | |
| Oil | <input checked="" type="radio"/> FAIR · Attn | |
| Exhaust Color | <input checked="" type="radio"/> FAIR · Attn | |
| US EPA | YES · <input checked="" type="radio"/> NO | |
| OPERATION PUMP | | |
| Sound | <input checked="" type="radio"/> FAIR · Attn | |
| Oil leakage | <input checked="" type="radio"/> FAIR · Attn | |
| Power | <input checked="" type="radio"/> FAIR · Attn | |
| COOLING SYSTEM | | |
| Radiator | <input checked="" type="radio"/> FAIR · Attn | |
| Oil Cooler | <input checked="" type="radio"/> FAIR · Attn | |
| TRANSMISSION & TRAVEL | | |
| T/M TYPE | <input checked="" type="radio"/> PS · DD | DIFF. STEERING <input checked="" type="radio"/> YES · NO |
| Transmission | <input checked="" type="radio"/> FAIR · Attn | |
| Travel | <input checked="" type="radio"/> FAIR · Attn | |
| INTERIOR See Photos. 写真参照 | | |
| INTERIOR COND. | CLEAN · <input checked="" type="radio"/> FAIR · DIRTY | |
| Operator's Seat | <input checked="" type="radio"/> FAIR · Attn | |
| Glasses | <input checked="" type="radio"/> FAIR · Attn | |
| AirCon | <input checked="" type="radio"/> A/C · H/C · H only · C only · None | |
| BLADE & CYLINDERS | | |
| BLADE | <input checked="" type="radio"/> FAIR · Attn | |
| CYLD.(R) | <input checked="" type="radio"/> FAIR · Attn | |
| CYLD.(L) | <input checked="" type="radio"/> FAIR · Attn | |
| TILT CYLD | <input checked="" type="radio"/> FAIR · Attn | |
| ANGLE CYLD | <input checked="" type="radio"/> FAIR · Attn | |

| | | | |
|--|--|--------|-----|
| UNDERCARRIAGE See Photos. 写真参照 | | | |
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | | | 2 |
| COMMENT | | | |
| | | | |
| Ripper | MULTI · S/S | Shanks | PCS |
| Ripper CYLD. | <input checked="" type="radio"/> FAIR · Attn | | |
| EQUALIZER BAR | <input checked="" type="radio"/> FAIR · Attn | | |
| COMMENT | | | |
| | | | |
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | | | 4 |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。