

INSPECTION SHEET 検品書
CRAWLER DRILL クローラドリル

INSPECTION DATE	2025/4/4	MAKE	INGERSOLL RAND	MODEL	CDH-831C
SERIAL	W00213700		STAMP	NOT FOUND	
HR METER	2362	HR	YEAR	YR	
CAB/CNP	<input checked="" type="radio"/> CAB /	<input type="radio"/> CNP /	<input type="radio"/> NONE	SHOE	300G
DRIFTER MODEL	YH-70S-9838510				

ENGINE : MODEL	S/N
Oil leakage	<input checked="" type="radio"/> FAIR · Attn
Blow-By	<input checked="" type="radio"/> FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn
Oil	<input checked="" type="radio"/> FAIR · Attn
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn
US EPA	YES · <input checked="" type="radio"/> NO
MAIN PUMP	
Sound	<input checked="" type="radio"/> FAIR · Attn
Oil leakage	<input checked="" type="radio"/> FAIR · Attn
Power	<input checked="" type="radio"/> FAIR · Attn
COOLING SYSTEM	
Radiator	<input checked="" type="radio"/> FAIR · Attn
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn
OPERATING SYSTEM	
Swing	<input checked="" type="radio"/> FAIR · Attn
Travel	<input checked="" type="radio"/> FAIR · Attn
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN · <input checked="" type="radio"/> FAIR · DIRTY
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn 破れあり HUGE CUT
Glasses	<input checked="" type="radio"/> FAIR · Attn
AirCon	A/C · <input checked="" type="radio"/> H/C · H only · C only · None
DRIFTER HYDR.	
Lift	<input checked="" type="radio"/> FAIR · Attn 油漏れあり OIL LEAKING
Swing	<input checked="" type="radio"/> FAIR · Attn
Tilt	<input checked="" type="radio"/> FAIR · Attn
Slide	<input checked="" type="radio"/> FAIR · Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
COMMENT	
Guide(Slide Length)	4500 mm
Rod Changer	<input checked="" type="radio"/> YES · NO
Drifter	<input checked="" type="radio"/> YES · NO
Compressor	<input checked="" type="radio"/> YES · NO
Blow	<input checked="" type="radio"/> YES · NO
COMMENT	
ガイドエクステンションシリンダー油漏れあり	
GUIDE SLIDE CYLINDER: OIL LEAKING	
右側オシレーションシリンダー油漏れあり	
RIGHT OSCILLATING CYLINDER: OIL LEAKING	
ガイドダンプシリンダー油漏れあり	
GUIDE DUMP CYLINDER: OIL LEAKING	
ヒーター&クーラー: 冷えない COOLER: MALFUNCTION	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。