

INSPECTION SHEET 検品書
ROLLER ローラー

INSPECTION DATE	2025/4/16	MAKE	HITACHI	MODEL	CP220-3		
SERIAL	HCM8UC00T00030223			STAMP	HCM8UC00T00030223		
HR METER	3396	HR	Odometer	8692	km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	14/70-20		

ENGINE : MODEL	S/N
Oil leakage	(FAIR) · Attn
Blow-By	(FAIR) · Attn A LITTLE · MIDDLE · SEVERE
Sound	(FAIR) · Attn
Oil	(FAIR) · Attn
Exhaust Color	(FAIR) · Attn
US EPA	YES · (NO)
OPERATION PUMP	
Sound	(FAIR) · Attn
Oil leakage	(FAIR) · Attn
Power	(FAIR) · Attn
COOLING SYSTEM	
Radiator	(FAIR) · Attn
Oil Cooler	(FAIR) · Attn
TRANSMISSION & TRAVEL	
T/M TYPE	(PS) · DD
Transmission	(FAIR) · Attn
Travel	(FAIR) · Attn
FOOT BRAKE	(FAIR) · Attn
PARKING BRAKE	(FAIR) · Attn
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN · (FAIR) · DIRTY
Operator's Seat	(FAIR) · Attn切れあり CUTS
Glasses	FAIR · Attn
AirCon	A/C · H/C · H only · C only · (None)
OTHERS	
Vibratory	FAIR · Attn
Watering	(FAIR) · Attn
Articulate	FAIR · Attn

UNDERCARRIAGE :	See Photos. 写真参照
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR	(FAIR) · WORN · UNEVEN WEAR
COMMENT 	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。