

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/4/18	MAKE	KOMATSU	MODEL	PC58UU-3
SERIAL	20648			STAMP	20648
HR METER	6821	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	400G PADS

ENGINE : MODEL		S/N
Oil leakage	☒ FAIR · Attn	
Blow-By	☒ FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	☒ FAIR · Attn	
Oil	☒ FAIR · Attn	
Exhaust Color	☒ FAIR · Attn	
US EPA	☒ YES · NO	
MAIN PUMP		
Sound	☒ FAIR · Attn	
Oil leakage	☒ FAIR · Attn	
Power	☒ FAIR · Attn	
COOLING SYSTEM		
Radiator	☒ FAIR · Attn	
Oil Cooler	☒ FAIR · Attn	
OPERATING SYSTEM		
Swing	☒ FAIR · Attn	
Travel	☒ FAIR · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · ☒ FAIR · DIRTY	
Operator's Seat	☒ FAIR · ☒ Attn	破れ大 CUTS
Glasses	☒ FAIR · Attn	
AirCon	A/C · H/C · H only · C only · ☒ None	
BOOM / ARM / BKT		
Boom	☒ FAIR · Attn	
Boom Cylinder	☒ FAIR · ☒ Attn	油漏れ小 OIL LEAKING
Arm	☒ FAIR · Attn	
Arm Cylinder	☒ FAIR · ☒ Attn	油漏れ小 OIL LEAKING
BKT	☒ FAIR · Attn	
BKT Cylinder	☒ FAIR · Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1
COMMENT	
左右キャリアローラーなし CARRIER ROLLERS: MISSING	
BKT	☒ STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · ☒ WRIST
Multi	☒ MULTI · 2 · NO
ARM-CRANE	☒ YES · NO *1
BLADE	☒ YES · NO *2
OFFSET	☒ YES · NO *3
OFFSET Cylinder	☒ FAIR · Attn
Piping	YES · ☒ NO Breaker only · Multi
COMMENT	
運転席下カバーなし LEFT COVER: MISSING	
ロー時ポンプに圧を掛けるとE/Gストップする(ポンプへたりあり)	
ENGINE STALLING WITH ENGINE LOAD INCREASING	
ON LOW ENGINE SPEED WORK	
(MAIN PUMP: DETERIORATED)	
*1 モニターの数字が見えない、フック変形あり	
*1 MONITOR: VERY BLURRED, HOOK: DISTORTED	
*2 腐食部分あり PARTLY CORRODED & HUGE HOLES	
*3 ペダル固着気味、干渉防止不良	
*3 PEDAL: A LITTLE STUCK,	
ANTI-INTERFERENCE SYSTEM: MALFUNCTION	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。